


Vehicle details

VIN	TMBLJ9NSX M8025133	Brand	SKODA	Maintenance date	-
Licence Plate	BN221NK	Model	Kodiaq 2,0 TDI Sportline 4x4 110KW	Maintenance mileage	-
Registration date	21/12/2020	Year	1000	Exterior Color	Grey Metallic
Odometer	154 915 km	Engine size	1968	interior Color	Black
Fuel	Diesel	Body Type	SUV CrossOver	Next technical inspection	01/12/2025
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	27/12/2024	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Panoramic roof	✓
Xenon projectors	✓
Anti-fog lights	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Heating seats	✓
Electric seats	✓
Tow	✓

Removable element



Technical Document

Spare key	✓
Remote key	✓

Tyres

Continental 235/45/20 V Summer 4.4 mm	Continental 235/45/20 V Summer 4.4 mm	Continental 235/45/20 V Summer 5.1 mm
Continental 235/45/20 V Summer 5.3 mm	Continental 235/45/20 V Summer 5.1 mm	

Exterior

1



Part	Roof
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

2



Part	Alloy wheel 20"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Replace

3



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

4



Part	Exterior door mirror shell
Position	Right
Damages	Scratched
Severity	-
Repair mode	Repair

5



Part	Alloy wheel 20"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Replace

Others

6



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint