

Inspection Protocol

TRADING
SOLUTIONS

SKODA OCTAVIA SCOUT 2.0 TDI 4X4

Vehicle information

License plate	RWG416	Inspected by	A.H.
Year model	2018	Date of inspection	2025-04-14
Manuf. year/month	2017-08	City	Falkenberg
First day in traffic	2017-08	Keys	2
Colour	Vit	Service book	Elektronisk servicebok
Mileage	138 290 km	Latest service	2021-03-17
Fuel	Diesel	Mileage at the latest service	88 800 km
Transmission	DSG Sekventiell	Summer tires	17" alu-fälg 6/6/6/6
Engine effect	135 kW	Winter tires	alu-fälg dubbat 5/6/6/5

Damages

Location	Damage	Comments	Costs excluding VAT
Service	Due now		450 €
Bumper, Rear	Paint retouch traces		0 €
Bonnet	Chip		70 €
Tak, Tak	Chip		70 €
Glass, Windshield	Chip		30 €
Total excl. VAT			620 €

Service occasions

3000-mil, 6000-mil

Images

[See all images in large format](#)

















Service Dags nu 5 000 kr











Stötfångare Bak Lackbättring 50 kr



Motorhuv Stenskott 800 kr



Tak Tak Stenskott 800 kr



Glas Vindruta Stenskott 300 kr





