



SKODA Roomster

Roomster 1.2 TSI

VIN NO TMBNN65J3C7017009

Registration Number J3C7017009



MOT Date



Last Service

2023-07-05

Number of Owners



Last Service Mileage

202161

Number of Keys



First Registration Date

2011-10-27

Odometer Reading



Country First Registered

-

251388 km

Inspection Report Summary

Customer

BCA Online

Report Number

P20250930102850

Inspection Date / Place

2025-09-30 / ARS Altmann
AG Wolnzach

Cosmetic Grade

5

Vehicle Summary

Vehicle Condition

Runner

VAT Type

Margin

Fuel Type

Petrol

Road Worthy

Yes

Colour

White

Engine Size (cc)

1197

Engine Size

1.2

No of Doors

5

Body Type

Stationwagon / Estate

Drive Train

Front

Seat Colour

No of Seats

5

Seat Covering Name

Seat Covering

Cloth

Charging Cables

NEDC CO2 Rating (q/km)

134

Gearbox Type

Manual

Vehicle History & Documents

Service Book Available

Present

Next Service Mileage


km

Previous Usage



Imported

No

Manufacturer Warrenty







Equipment

Airbag Status	Heated wing mirrors	Remote central locking	Stability control
Central locking	Radio	Anti-lock braking	Remote adjusting wing mirrors
Roof rails	CD Player	Leather steering wheel	

Equipment Details


Air Conditioning	Climate Control	Extra Wheel / Tyre Set	Summer Tyres - Alloy
Seat Heating	Front		

Wheels & Tyres


Extra Wheel - 1 Tyre Depth	2	Extra Wheel - 2 Tyre Depth	2
Extra Wheel - 3 Tyre Depth	2	Extra Wheel - 4 Tyre Depth	2
Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage

22 Schäden



4 Schäden




Component		Damage	Comments
1	Door / Back Right	Paint / Poor Previous Repair	
2	Door / Front Left	Bodywork / Dent / Dent	
3	Roof	Bodywork / Dent / Dent	
4	Fender / Front Right	Bodywork / Dent / Dent	
5	Hood	Bodywork / Dent / Dent	
6	Bumper / Front	Paint / Scratch / Scuff	
7	Grille / Front	Bodywork / Breakage / Hole	
8	Wing Repeater / Left	Bodywork / Dent / Dent	
9	Rocker Panel / Center Left	Paint / Corrosion	
10	Door / Front Left	Paint / Scratch / Scuff	
11	Seat / Front Left	Interior / Scratched	
12	Panel Filling / Front Left	Interior / Dirty	


13	Pillar / Back Left	Bodywork / Dent / Dent
14	Seat / Back Center	Interior / Dirty
15	Side Panel / Back Left	Paint / Corrosion
16	Bumper / Back	Paint / Scratch / Scuff
17	Bumper / Back	Paint / Scratch / Scuff
18	Tailgate	Paint / Corrosion
19	Antenna Rod	Out of Bodywork / Breakage
20	Tailgate	Bodywork / Dent / Dent
21	Side Panel / Back Right	Paint / Corrosion
22	Rocker Panel / Center Right	Paint / Corrosion
23	Door / Front Right	Paint / Scratch / Scuff
24	Seat / Front Right	Interior / Dirty
25	Fender / Front Right	Paint / Corrosion
26	Bumper / Front	Paint / Scratch / Scuff




1. Door / Back Right
Paint / Poor Previous Repair -



2. Door / Front Left
Bodywork / Dent / Dent -



3. Roof
Bodywork / Dent / Dent -



4. Fender / Front Right
Bodywork / Dent / Dent -



5. Hood
Bodywork / Dent / Dent -



6. Bumper / Front
Paint / Scratch / Scuff -



7. Grille / Front
Bodywork / Breakage / Hole -



8. Wing Repeater / Left
Bodywork / Dent / Dent -



9. Rocker Panel / Center Left
Paint / Corrosion -



10. Door / Front Left
Paint / Scratch / Scuff -



11. Seat / Front Left
Interior / Scratched -




12. Panel Filling / Front Left
Interior / Dirty -



13. Pillar / Back Left
Bodywork / Dent / Dent -



14. Seat / Back Center
Interior / Dirty -



15. Side Panel / Back Left
Paint / Corrosion -




16. Bumper / Back
Paint / Scratch / Scuff -



17. Bumper / Back
Paint / Scratch / Scuff -



18. Tailgate
Paint / Corrosion -



19. Antenna Rod
Out of Bodywork / Breakage -



20. Tailgate
Bodywork / Dent / Dent -




21. Side Panel / Back Right
Paint / Corrosion -



22. Rocker Panel / Center Right
Paint / Corrosion -



23. Door / Front Right
Paint / Scratch / Scuff -



24. Seat / Front Right
Interior / Dirty -



25. Fender / Front Right
Paint / Corrosion -



26. Bumper / Front
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

ABS Warning Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	!	ESP Fault/Traction Control Malfunction Light	!
Display Defect	✓	Service Light	!
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	!	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓		

Levels

Brakes Fluid	NA	Coolant Fluid	!
--------------	----	---------------	---

Test Drive Inspection

Brake

Brake System Anomaly 

Steering Wheel

Steering | Noise / Anomaly 

Engine

Engine Noise  The Gears Scratch / Skip / Abnormal Operation 

Fume Quantity  Power Loss 

Clutch

Clutch Functioning 

General

Test Driven Status 

-  **No troubles detected, good condition or correct tests, according to vehicle age and mileage**
-  **Damages or malfunction detected that requires repairs by the buyer**
-  **Not applicable**
-  **Not tested**

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)