



SUZUKI Ignis

Ignis 1.3

VIN NO TSMMHX51S00194893
Registration Number 1S00194893



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-04-01	3	2	173030 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2023-04-11	129457	2005-02-24	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250912102328
Inspection Date / Place	2025-09-12 / BCA Berlin	Cosmetic Grade	4

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Unknown
Colour	Red	Engine Size (cc)	1328
Engine Size	1.3	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	154
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Remote adjusting wing mirrors	CD Player	Anti-lock braking
Remote central locking	Radio		

Equipment Details


Air Conditioning	Yes
------------------	-----

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	4	Left Rear Tyre Depth	5

Cosmetic Damage


5 Schäden



2 Schäden



Component		Damage	Comments
1	Seat / Front Left	Interior / Dirty	
2	Seat / Front Right	Interior / Dirty	
3	Shutter Cap / Front	Missing Part	
4	Windshield / Front	Paint / Chipping	
5	Bumper / Front	Bodywork / Breakage / Crack	
6	Side Panel / Back Right	Bodywork / Dent / Dent	
7	Bumper / Back	Paint / Scratch / Scuff	




1. Seat / Front Left
Interior / Dirty -



2. Seat / Front Right
Interior / Dirty -



3. Shutter Cap / Front
Missing Part -



4. Windshield / Front
Paint / Chipping -



5. Bumper / Front
Bodywork / Breakage / Crack -



6. Side Panel / Back Right
Bodywork / Dent / Dent -



7. Bumper / Back
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Audio Equipment	!	AC / Heating System	✓
Other Equipments	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly !

Engine

Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓

Clutch

Clutch Functioning ✓

Brake

Brake System Anomaly ✓

General

Test Driven Status ✓

✓ **No troubles detected, good condition or correct tests, according to vehicle age and mileage**

9/10 - Report Number P20250912102328

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)