


Vehicle details

VIN	U5YH2511A LL104109	Brand	KIA	Maintenance date	-
Licence Plate	J8-00-NH	Model	CEED 1.0 T-GDi DynamicL	Maintenance mileage	-
Registration date	24/09/2020	Year	2020	Exterior Color	Blue Metallic
Odometer	149 386 km	Engine size	998	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	19/12/2024	Inspection loc.	LCC3 Alphen Leseman
-----------------	------------	-----------------	---------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓


Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres



Exterior

3



Part	Bumper
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

4



Part	Tailgate / Boob door
Position	Back left
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

5



Part	Wing
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

6



Part	Door
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

7



Part	Step plate
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	For info

8



Part	Upper door
Position	Front right
Damages	Dented
Severity	-
Repair mode	For info

9



Part	Bumper
Position	Front
Damages	Dent & Chips
Severity	-
Repair mode	Repair

10



Part	Grille with fog lights
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Repair

11



Part	Bonnet
Position	-
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

Interior damage

1



Part	Seat
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

2



Part	Seat
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning