


Vehicle details

VIN	U5YH5F11A LL033066	Brand	KIA	Maintenance date	01/01/1900
Licence Plate	H5-12-VF	Model	XCeed 1.0 T-Gdi ActieAuto 5d DynamicLine APL	Maintenance mileage	-
Registration date	06/06/2020	Year	2020	Exterior Color	White Solid
Odometer	65 817 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	03/06/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Tow	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

Spare key	✗
User manual	✓
Warranty booklet	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 235/45/18 Summer 5.0 mm	Michelin 235/45/18 Summer 5.5 mm
Continental 235/45/18 Summer 7.0 mm	Continental 235/45/18 Summer 7.0 mm

Exterior

1



●●

Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

2



●●●

Part	Alloy wheel 18"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

4



●●●●

Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

5



●●

Part	Roof
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

6



●●

Part	Door
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

Interior damage

3

A photograph showing a red folder with the text 'Gründungs & Unternehmensplan' and 'für den kleinen Businessplan' on its cover. Next to it is a black spare key. They are resting on a dark, textured surface, possibly a car's interior.

Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

Comments

Opslagpark : Dekra Ayvens