



KIA Sportage IV 2016 Diesel
Sportage 1.7 crdi Class 2wd 115cv my17

VIN NO U5YPH815AJL516793
Registration Number FS507HT



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2024-11-26	-	-	147600 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2018-11-05	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250918121241
Inspection Date / Place	2025-09-18 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1685
Engine Size	1.7	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	124

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment

Central locking	Rear parking sensors	Digital Radio	Satellite navigation
Parcel Shef	Remote central locking	Trip Computer	Stability control
Power assisted steering	Alloys wheels	Electrically folding wing mirrors	Volante multifuncion
Remote adjusting wing mirrors	Cruise control	Tyre Mobility Kit	


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Summer	
	HANKOOK HANKOOK-VENTUS S1 EVO3 K127	245/45//R19 - 102Y / 3 mm
	HANKOOK HANKOOK-VENTUS S1 EVO3 K127	245/45//R19 - 102Y / 3 mm
	HANKOOK HANKOOK-VENTUS S1 EVO3 K127	245/45//R19 - 102Y / 3 mm
	HANKOOK HANKOOK-VENTUS S1 EVO3 K127	245/45//R19 - 102Y / 3 mm

Cosmetic Damage

25 Danni



2 Danni




Component		Damage	Comments
1	Center Console	Interior / Broken	
2	Seat / Front Left	Interior / Ripped	
3	Windshield / Front	Glass Break / Impact	
4	Hood	Paint / Chipping	
5	Hood	Bodywork / Dent / Hail Area	
6	Bumper / Front	Bodywork / Dent	
7	Rim / Front Left	Out of Bodywork / Scratch	
8	Fender / Front Left	Bodywork / Poor Previous Repair	
9	Mirror Shell / Front Left	Paint / Scratch / Line	
10	Door / Front Left	Bodywork / Dent	
11	Door / Back Left	Paint / Scratch / Line	
12	Rim / Back Left	Out of Bodywork / Scratch	

13	Fender / Back Left	Paint / Scratch / Line
14	Bumper / Back	Bodywork / Dent
15	Tailgate	Bodywork / Dent
16	Fender / Back Right	Bodywork / Dent
17	Tire / Back Right	Tire
18	Rim / Back Right	Out of Bodywork / Scratch
19	Door / Back Right	Bodywork / Dent
20	Door / Front Right	Bodywork / Dent
21	Fender / Front Right	Paint / Scratch / Line
22	Tire / Front Right	Tire
23	Rim / Front Right	Out of Bodywork / Scratch
24	Door / Front Right	Bodywork / Dent / Positive
25	Roof	Bodywork / Dent / Hail Area
26	Front Light / Front Left	Glass Break / Scratch
27	Front Light / Front Left	Glass Break / Scratch



1. Center Console
Interior / Broken -



2. Seat / Front Left
Interior / Ripped -



3. Windshield / Front
Glass Break / Impact -



4. Hood
Paint / Chipping -



5. Hood
Bodywork / Dent / Hail Area -




6. Bumper / Front
Bodywork / Dent -



7. Rim / Front Left
Out of Bodywork / Scratch -



8. Fender / Front Left
Bodywork / Poor Previous Repair -



9. Mirror Shell / Front Left
Paint / Scratch / Line -



10. Door / Front Left
Bodywork / Dent -




11. Door / Back Left
Paint / Scratch / Line -



12. Rim / Back Left
Out of Bodywork / Scratch -



13. Fender / Back Left
Paint / Scratch / Line -



14. Bumper / Back
Bodywork / Dent -



15. Tailgate
Bodywork / Dent -



16. Fender / Back Right
Bodywork / Dent -



17. Tire / Back Right
Tire - Replace



18. Rim / Back Right
Out of Bodywork / Scratch -



19. Door / Back Right
Bodywork / Dent -



20. Door / Front Right
Bodywork / Dent -



21. Fender / Front Right
Paint / Scratch / Line -




22. Tire / Front Right
Tire - Replace



23. Rim / Front Right
Out of Bodywork / Scratch -



24. Door / Front Right
Bodywork / Dent / Positive -



25. Roof
Bodywork / Dent / Hail Area -



26. Front Light / Front Left
Glass Break / Scratch -



27. Front Light / Front Left
Glass Break / Scratch -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	!

Test Drive Inspection

Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	✓		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			