



DACIA DOKKER Dokker TCE 115 Lauréate

VIN NO UU10SDA0549265364

Registration Number CW467NJ



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



2013-07-03

Odometer Reading



123916 km

Country First Registered



Inspection Report Summary


Customer	BCA Auto Encheres	Report Number	P20250523085431
Inspection Date / Place	2025-05-23 / BCA BETHUNE	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Petrol	Gearbox Type	Manual
Colour	Blue	Engine Size (cc)	1198
Engine Size	1.2	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (g/km)	135

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warranty			



Equipment


Central locking	Rear parking sensors	Cruise control	Power assisted steering
Radio	Alloys wheels	Front fog lamps	Roof rails

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Cosmetic Damage

21 Dommages



2 Dommages



Component		Damage	Comments
1	Floor Carpet	Interior / Dirty	
2	Floor Carpet	Interior / Dirty	
3	Corner Bumper / Front Right	Paint / Scratch / Scuff	
4	Bumper / Front	Paint / Scratch / Scuff	
5	Corner Bumper / Front Left	Paint / Scratch / Scuff	
6	Fender / Front Left	Paint / Scratch / Line	
7	Rim / Front Left	Out of Bodywork / Scratch	
8	Door / Front Left	Paint / Scratch / Line	
9	Door / Back Left	Paint / Scratch / Scuff	
10	Door / Back Left	Paint / Scratch / Line	
11	Rim / Back Left	Out of Bodywork / Scratch	
12	Corner Bumper / Back Left	Paint / Scratch / Scuff	
13	Bumper / Back	Paint / Scratch / Scuff	

14	Corner Bumper / Back Right	Paint / Scratch / Scuff
15	Tailgate	Paint / Poor Previous Repair
16	Side Panel / Back Right	Paint / Scratch / Scuff
17	Rim / Back Right	Out of Bodywork / Scratch
18	Door / Back Right	Paint / Scratch / Line
19	Door / Back Right	Paint / Scratch / Line
20	Door / Front Right	Paint / Scratch / Line
21	Mirror / Front Right	Paint / Chipping
22	Rim / Front Right	Out of Bodywork / Scratch
23	Roof	Paint / Scratch / Scuff



1. Floor Carpet
Interior / Dirty -



2. Floor Carpet
Interior / Dirty -




3. Corner Bumper / Front Right
Paint / Scratch / Scuff -



4. Bumper / Front
Paint / Scratch / Scuff -



5. Corner Bumper / Front Left
Paint / Scratch / Scuff -



6. Fender / Front Left
Paint / Scratch / Line -



7. Rim / Front Left
Out of Bodywork / Scratch -



8. Door / Front Left
Paint / Scratch / Line -



9. Door / Back Left
Paint / Scratch / Scuff -



10. Door / Back Left
Paint / Scratch / Line -



11. Rim / Back Left
Out of Bodywork / Scratch -



12. Corner Bumper / Back Left
Paint / Scratch / Scuff -




13. Bumper / Back
Paint / Scratch / Scuff -



14. Corner Bumper / Back Right
Paint / Scratch / Scuff -




15. Tailgate
Paint / Poor Previous Repair -



16. Side Panel / Back Right
Paint / Scratch / Scuff -



17. Rim / Back Right
Out of Bodywork / Scratch -



18. Door / Back Right
Paint / Scratch / Line -



19. Door / Back Right
Paint / Scratch / Line -



20. Door / Front Right
Paint / Scratch / Line -



21. Mirror / Front Right
Paint / Chipping -



22. Rim / Front Right
Out of Bodywork / Scratch -



23. Roof
Paint / Scratch / Scuff -

Mechanical Condition


Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.