



DACIA Lodgy

Lodgy dCi 110

VIN NO UU1JSDF9654353382
Registration Number 9654353382



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	1	2	189308 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2016-02-18	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250929103554
Inspection Date / Place	2025-09-29 / ARS Altmann AG Riedstadt	Cosmetic Grade	4


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	1461
Engine Size	1.5	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	105
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tow ball	Airbag Status	Anti-lock braking	Remote adjusting wing mirrors
Satellite navigation	Leather steering wheel	Rear parking sensors	Trip Computer
Alloys wheels	Bluetooth telephone interface	Remote central locking	Stability control
Radio			

Equipment Details


Tow Ball Type	Static	Air Conditioning	Yes
Alloy Wheel Size	16	Seat Heating	No

Wheels & Tyres


Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage

22 Schäden




0 Schäden



Component		Damage	Comments
1	Hood	Bodywork / Dent / Dent	
2	Blade/spoiler / Front	Paint / Scratch / Scuff	
3	Bumper / Front	Paint / Scratch / Scuff	
4	Rim / Front Left	Out of Bodywork / Scratch	
5	Fender / Front Left	Bodywork / Dent / Dent	
6	Door / Front Left	Bodywork / Dent / Dent	
7	Door / Front Left	Paint / Scratch / Scuff	
8	Pillar / Front Left	Bodywork / Dent / Dent	
9	Bumper / Back	Paint / Scratch / Scuff	
10	Tailgate	Paint / Scratch / Scuff	
11	Fender / Back Right	Bodywork / Dent / Dent	
12	Rim / Back Right	Out of Bodywork / Scratch	

13	Bumper / Back	Paint / Scratch / Scuff
14	Pillar / Back Right	Bodywork / Dent / Dent
15	Door / Back Right	Bodywork / Dent / Dent
16	Door / Front Right	Bodywork / Dent / Dent
17	Door / Front Right	Paint / Scratch / Scuff
18	Pillar / Front Right	Bodywork / Dent / Dent
19	Fender / Front Right	Paint / Scratch / Scuff
20	Rim / Front Right	Out of Bodywork / Scratch
21	Fender / Back Left	Paint / Poor Previous Repair
22	Door / Front Left	Paint / Scratch / Scuff



1. Hood
Bodywork / Dent / Dent -




2. Blade/spoiler / Front
Paint / Scratch / Scuff -




3. Bumper / Front
Paint / Scratch / Scuff -




4. Rim / Front Left
Out of Bodywork / Scratch -



5. Fender / Front Left
Bodywork / Dent / Dent -




6. Door / Front Left
Bodywork / Dent / Dent -



7. Door / Front Left
Paint / Scratch / Scuff -




8. Pillar / Front Left
Bodywork / Dent / Dent -



9. Bumper / Back
Paint / Scratch / Scuff -



10. Tailgate
Paint / Scratch / Scuff -



11. Fender / Back Right
Bodywork / Dent / Dent -




12. Rim / Back Right
Out of Bodywork / Scratch -



13. Bumper / Back
Paint / Scratch / Scuff -



14. Pillar / Back Right
Bodywork / Dent / Dent -




15. Door / Back Right
Bodywork / Dent / Dent -



16. Door / Front Right
Bodywork / Dent / Dent -



17. Door / Front Right
Paint / Scratch / Scuff -



18. Pillar / Front Right
Bodywork / Dent / Dent -



19. Fender / Front Right
Paint / Scratch / Scuff -



20. Rim / Front Right
Out of Bodywork / Scratch -



21. Fender / Back Left
Paint / Poor Previous Repair -



22. Door / Front Left
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓

Equipments Test

Other Equipments	✓	Central Locking	✓
Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Clutch

Clutch Functioning

Brake

Brake System Anomaly

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)