



# DACIA DOKKER

## Dokker TCe 130 FAP Stepway

VIN NO UU1K6720264651840

Registration Number FL832XW



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



### Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250922085621
Inspection Date / Place	2025-09-22 / BCA MONTMARTIN	Cosmetic Grade	1

### Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Petrol	Gearbox Type	Manual
Colour	Light Grey	Engine Size (cc)	1333
Engine Size	1.3	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	138

### Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment


Central locking	Rear parking sensors	Tow ball	Front fog lamps
Roof rails	Radio	Stability control	Cruise control
Power assisted steering	Satellite navigation		

Equipment Details


Seat Heating	No	Air Conditioning	Yes
--------------	----	------------------	-----

Cosmetic Damage

5 Dommages



2 Dommages



Component		Damage	Comments
1	Seat / Front Left	Interior / Stained	
2	Seat / Back Center	Interior / Stained	
3	Rim / Front Left	Out of Bodywork / Scratch	
4	Door / Back Left	Paint / Scratch / Line	
5	Rim / Back Left	Out of Bodywork / Scratch	
6	Rim / Back Right	Out of Bodywork / Scratch	
7	Rim / Front Right	Out of Bodywork / Scratch	



1. Seat / Front Left  
Interior / Stained -



2. Seat / Back Center  
Interior / Stained -



3. Rim / Front Left  
Out of Bodywork / Scratch -



4. Door / Back Left  
Paint / Scratch / Line -



5. Rim / Back Left  
Out of Bodywork / Scratch -



6. Rim / Back Right  
Out of Bodywork / Scratch -





7. Rim / Front Right  
Out of Bodywork / Scratch -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

*The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.*