



DACIA DOKKER: 1YBT772			
Vinnumber:	UU1K6720265503150	Versionname:	TCe 130 GPF Stepway
First Registrationdate:	9/07/2020	Fiscalpower:	
Expertise Mileage:	100012	Power Kw:	96
Bodytype:		Body colour	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel
Transmission:		Parking lot	3709
Fueltype:	Petrol		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Options			
Number of keys total	2	Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		
Limited Technical Inspection			
Tyres			
Summer tyres:	195/55/16/92 H		
	Fr.L.	Firestone: 5 mm	Fr.R. Firestone: 5 mm
	Re.L.	Firestone: 5 mm	Re.R. Firestone: 5 mm
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			195/55 R 16 92 H
Tyre size FR			195/55 R 17 92 H
Tyre size RL			195/55 R 17 92 H
Tyre size RR			195/55 R 17 92 H
Tyre type FL			All seasons
Tyre type FR			All Seasons
Tyre type RL			All seasons
Tyre type RR			All Seasons
Tyre make FL			258
Tyre make FR			258
Tyre make RL			258
Tyre make RR			258
Assistance equipment			
Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			587,42
Interior, Damaged, Acceptable			0,00



Dashboard, Scratch(es), Acceptable	0,00
------------------------------------	------



Door panel FL, Scratch(es), Acceptable	0,00
--	------



Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------



Bumper moulding F, Scratch(es), Smart repair	113,74
--	--------



Wheel cover FL, Scratch(es), Acceptable	0,00
---	------



Door FL, Dent(s) and scratch(es), Acceptable	0,00
--	------



Step L, Dent(s) and scratch(es), Repair and paint (complete)	157,71
--	--------



Bumper R, Scratch(es), Smart repair	113,74
-------------------------------------	--------



Boot door panel RR, Scratch(es), Acceptable	0,00
---	------



Boot door panel RL, Scratch(es), Acceptable	0,00
---	------



Wheel cover FR, Scratch(es), Replace	44,52
--------------------------------------	-------



Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Step R, Dent(s) and scratch(es), Repair and paint (complete)	157,71
--	--------

