



# RENAULT CAPTUR

## Captur TCe 120 Energy EDC Intens

VIN NO VF12R031A57350879

Registration Number EP261JP



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



### Inspection Report Summary

Customer	BCA Auto Encheres	Report Number	P20251010095501
Inspection Date / Place	2025-10-10 / BCA GUERLESQUIN	Cosmetic Grade	5

### Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Petrol	Gearbox Type	Automatic
Colour	Blue	Engine Size (cc)	1197
Engine Size	1.2	No of Doors	5
Family	Passenger Car	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	125
Engine Rating CV		Metalic Colour	Yes
Accident Damage	No	Euro Emission	

### Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment


Central locking	Radio	Alloys wheels	Cruise control
Front parking sensors	Electrically folding wing mirrors	Rear parking sensors	Stability control
Front fog lamps	Power assisted steering		

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Cosmetic Damage

17 Dommages



1 Dommages



Component		Damage	Comments
1	Fender / Front Left	Paint / Scratch / Scuff	
2	Tailgate	Paint / Scratch / Scuff	
3	Fender / Front Right	Paint / Scratch / Scuff	
4	Gear Knob	Interior / Loose	
5	Fender / Front Right	Paint / Scratch / Scuff	
6	Fender / Front Right	Paint / Scratch / Scuff	
7	Side Panel / Back Right	Paint / Scratch / Scuff	
8	Tailgate	Paint / Scratch / Scuff	
9	Side Panel / Back Right	Paint / Scratch / Scuff	
10	Side Panel / Back Right	Paint / Stone Chip	
11	Side Panel / Back Right	Paint / Scratch / Scuff	
12	Side Panel / Back Right	Paint / Scratch / Scuff	

13	Tailgate	Missing Part
14	Side Panel / Back Right	Paint / Scratch / Scuff
15	Fender / Front Left	Paint / Scratch / Scuff
16	Fender / Front Left	Paint / Stone Chip
17	Fender / Front Left	Paint / Scratch / Scuff
18	Side Panel / Back Right	Paint / Chipping





1. Fender / Front Left  
Paint / Scratch / Scuff -



2. Tailgate  
Paint / Scratch / Scuff -



3. Fender / Front Right  
Paint / Scratch / Scuff -



4. Gear Knob  
Interior / Loose -



5. Fender / Front Right  
Paint / Scratch / Scuff -



6. Fender / Front Right  
Paint / Scratch / Scuff -





7. Side Panel / Back Right  
Paint / Scratch / Scuff -



8. Tailgate  
Paint / Scratch / Scuff -



9. Side Panel / Back Right  
Paint / Scratch / Scuff -



10. Side Panel / Back Right  
Paint / Stone Chip -



11. Side Panel / Back Right  
Paint / Scratch / Scuff -



12. Side Panel / Back Right  
Paint / Scratch / Scuff -





13. Tailgate  
Missing Part -



14. Side Panel / Back Right  
Paint / Scratch / Scuff -



15. Fender / Front Left  
Paint / Scratch / Scuff -



16. Fender / Front Left  
Paint / Stone Chip -



17. Fender / Front Left  
Paint / Scratch / Scuff -



18. Side Panel / Back Right  
Paint / Chipping -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

*The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.*