



RENAULT Clio

Clio Grandtour TCe 120 EDC

VIN NO VF17R400E52920637

Registration Number 0E52920637



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Online	Report Number	P20250925131600
Inspection Date / Place	2025-09-25 / ARS Altmann AG Wolnzach	Cosmetic Grade	4

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Brown	Engine Size (cc)	1197
Engine Size	1.2	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	120
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warranty			







Equipment

USB Socket	Alloys wheels	Auxiliary Socket	Cruise control
Remote adjusting wing mirrors	Roof rails	Stability control	Electrically folding wing mirrors
Radio	Airbag Status	Anti-lock braking	Bluetooth telephone interface
Front fog lamps	Remote central locking	Satellite navigation	Central locking
Leather steering wheel	Rear parking sensors		

Equipment Details


Air Conditioning	Yes	Alloy Wheel Size	16
Extra Wheel / Tyre Set	Summer Tyres - Alloy	Seat Heating	No

Wheels & Tyres

Extra Wheel - 1 Tyre Depth	5	Extra Wheel - 2 Tyre Depth	5
Extra Wheel - 3 Tyre Depth	4	Extra Wheel - 4 Tyre Depth	4
Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

20 Schäden




0 Schäden




Component		Damage	Comments
1	Hood	Bodywork / Dent / Dent	
2	Hood	Bodywork / Dent / Dent	
3	Door / Front Left	Bodywork / Dent / Dent	
4	Side Panel / Back Left	Bodywork / Dent / Dent	
5	Side Panel / Back Right	Bodywork / Dent / Dent	
6	Side Panel / Back Right	Bodywork / Dent / Dent	
7	Bumper / Front	Paint / Scratch / Scuff	
8	Rim / Front Left	Out of Bodywork / Scratch	
9	Wing Repeater / Left	Paint / Scratch / Scuff	
10	Door / Front Left	Paint / Scratch / Scuff	
11	Door / Back Left	Paint / Scratch / Scuff	
12	Side Panel / Back Left	Paint / Scratch / Scuff	


13	Rim / Back Left	Out of Bodywork / Scratch
14	Bumper / Back	Paint / Scratch / Scuff
15	Rim / Back Right	Out of Bodywork / Scratch
16	Door / Front Right	Paint / Scratch / Scuff
17	Pillar / Front Right	Bodywork / Dent / Dent
18	Mirror Shell / Front Right	Paint / Scratch / Scuff
19	Rim / Front Right	Out of Bodywork / Scratch
20	Bumper / Front	Paint / Scratch / Scuff




1. Hood
Bodywork / Dent / Dent -




2. Hood
Bodywork / Dent / Dent -




3. Door / Front Left
Bodywork / Dent / Dent -



4. Side Panel / Back Left
Bodywork / Dent / Dent -




5. Side Panel / Back Right
Bodywork / Dent / Dent -




6. Side Panel / Back Right
Bodywork / Dent / Dent -



7. Bumper / Front
Paint / Scratch / Scuff -



8. Rim / Front Left
Out of Bodywork / Scratch -



9. Wing Repeater / Left
Paint / Scratch / Scuff -



10. Door / Front Left
Paint / Scratch / Scuff -



11. Door / Back Left
Paint / Scratch / Scuff -



12. Side Panel / Back Left
Paint / Scratch / Scuff -



13. Rim / Back Left
Out of Bodywork / Scratch -



14. Bumper / Back
Paint / Scratch / Scuff -




15. Rim / Back Right
Out of Bodywork / Scratch -



16. Door / Front Right
Paint / Scratch / Scuff -



17. Pillar / Front Right
Bodywork / Dent / Dent -



18. Mirror Shell / Front Right
Paint / Scratch / Scuff -



19. Rim / Front Right
Out of Bodywork / Scratch -



20. Bumper / Front
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	!
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Audio Equipment	✓	AC / Heating System	✓
Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Parking Sensors / Cameras Functioning	✓		

Levels

Brakes Fluid	NA	Coolant Fluid	✓
--------------	----	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)