


## Vehicle details

|                   |                    |              |                                  |                           |             |
|-------------------|--------------------|--------------|----------------------------------|---------------------------|-------------|
| VIN               | VF17RE20A 59378347 | Brand        | RENAULT                          | Maintenance date          | -           |
| Licence Plate     | RN-98-0X           | Model        | Clio Estate Energy TCe 90 Zen 5d | Maintenance mileage       | -           |
| Registration date | 07/02/2018         | Year         | 2018                             | Exterior Color            | White Solid |
| Odometer          | 135 962 km         | Engine size  | 898                              | interior Color            | Grey        |
| Fuel              | Petrol             | Body Type    | -                                | Next technical inspection | -           |
| Seats             | -                  | Transmission | Manual                           | CO2                       | -           |
| Doors             | 5                  | Gears        | 5                                |                           |             |

## Inspection Details

|                 |            |                 |              |
|-----------------|------------|-----------------|--------------|
| Inspection date | 14/08/2025 | Inspection loc. | Dekra Ayvens |
|-----------------|------------|-----------------|--------------|



## Generic equipment

|                         |   |
|-------------------------|---|
| Manual air-conditioning | ✓ |
| Cruise control          | ✓ |
| GPS system              | ✓ |
| Central locking         | ✓ |
| Electric windows        | ✓ |
| Side rails              | ✓ |
| Park Distance Control   | ✓ |
| Audio System            | ✓ |

## Removable element


|                 |   |
|-----------------|---|
| Spare wheel kit | ✓ |
| Load cover      | ✓ |

## Technical Document

|                         |   |
|-------------------------|---|
| User manual             | ✓ |
| Warranty booklet        | ✓ |
| Spare key               | ✓ |
| Remote key              | ✓ |
| Sat Nav CD ROM Software | ✓ |

## Tyres

Continental 195/55/16 H Summer  
6.0 mm



Continental 195/55/16 H Summer  
6.0 mm



Continental 195/55/16 H Summer  
6.0 mm

Continental 195/55/16 H Summer  
6.0 mm

## Exterior

1



●●●

|             |                    |
|-------------|--------------------|
| Part        | Roof               |
| Position    | -                  |
| Damages     | Hail damaged       |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

2



●●●

|             |                    |
|-------------|--------------------|
| Part        | Bonnet             |
| Position    | -                  |
| Damages     | Hail damaged       |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

3



●●

|             |                    |
|-------------|--------------------|
| Part        | Roof post A/B/C    |
| Position    | Left               |
| Damages     | Hail damaged       |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |


4



●●

|             |              |
|-------------|--------------|
| Part        | Windscreen   |
| Position    | -            |
| Damages     | Stone impact |
| Severity    | -            |
| Repair mode | For info     |

5



●●

|             |                  |
|-------------|------------------|
| Part        | Door             |
| Position    | Front right      |
| Damages     | Chemical deposit |
| Severity    | -                |
| Repair mode | Lumpsum repair   |