














**TECHNICAL CONDITION** 

Engine	Brakes	Steering
Engine starts 	Brake operation 	Sounds normal 
Engine operation 		
Engine compartment dry (oil) 	Clutch	Gear Box
Fume quantity 	Clutch operation 	Automatic shift 
Sounds normal 	Idle sounds normal 	Manual shif 
	Clutch biting point 	Warning light OK 






**COMPLAINT NOTE** 

The technical check includes a visual check of the vehicles without removal of any components.  
The condition of the mechanical components cannot be rated.

**LEVELS** 

Coolant fluid 
Brakes fluid 





**EQUIPMENT TEST** 

Electric windows test 
Audio equipment 
Navigation equipment 
AC / Heating system 
Central lock system test 













**TYRES** 


Profile depths	
FL 4 mm	FR 4 mm
BR 5 mm	BL 5 mm


Additional tyre profil depths


A 	B 
C 	D 

**CONTROL LIGHTS** 

Dashboard 
ABS 
Oil 
Airbag 
Engine 
Brakes 
Steering 
DPF 
Diesel heaters 
Traction control / ESP / Stability control 
4x4 
Alternator / Battery 

 No defects recognizable, good condition or positive tests based on vehicle's age and mileage.

 Registered damage that needs to be repaired by the buyer.

 Not verifiable.