


Vehicle details

VIN	VF1FL0000 65557650	Brand	RENAULT	Maintenance date	27/05/2024
Licence Plate	BEB11H	Model	TraficFourgon-2014	Maintenance mileage	85 137 km
Registration date	12/11/2020	Year	2020	Exterior Color	Other
Odometer	116 914 km	Engine size	-	interior Color	
Fuel	Diesel	Body Type	Saloon / Hatchback	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	6		

Inspection Details

Inspection date	16/10/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Manual air-conditioning	✓
Bluetooth	✓
Automatic Gearbox	✓
Central locking	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel (wheel & tyre)	✗
Towing hook	✓

Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Spare key	✓
Key	✓
Remote key	✓

Tyres

Goodyear 215/65/16 H Summer 7.0 mm	Goodyear 215/65/16 H Summer 7.0 mm
Goodyear 215/65/16 H Summer 7.0 mm	Goodyear 215/65/16 H Summer 7.0 mm

Winter kit

Nokian 215/65/16 R Winter 6.0 mm	Nokian 215/65/16 R Winter 6.0 mm
Nokian 215/65/16 R Winter 6.0 mm	Nokian 215/65/16 R Winter 6.0 mm

Damages
1


Part	Service
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum

2


Part	Spare wheel (wheel & tyre)
Position	-
Damages	Missing
Severity	-
Repair mode	For info

3


Part	Engine cover
Position	-
Damages	Broken
Severity	-
Repair mode	Lumpsum replacement

4



Part	Door
Position	Back left
Damages	Dented
Severity	-
Repair mode	Lumpsum repair

5


Part	Wing
Position	Back left
Damages	Dented
Severity	-
Repair mode	Lumpsum repair

6


Part	Unpainted bumper
Position	Back
Damages	Damaged
Severity	-
Repair mode	Smart Repair

7


Part	Wing
Position	Back right
Damages	Dented
Severity	-
Repair mode	For info

8


Part	Door
Position	Back right
Damages	Dented
Severity	-
Repair mode	Lumpsum repair

9


Part	Bumper grille
Position	Front
Damages	Not conform
Severity	-
Repair mode	For info

10


Part	Unpainted bumper
Position	Front
Damages	Damaged
Severity	-
Repair mode	Smart Repair

11


Part	Exterior door mirror shell
Position	Front left
Damages	Damaged
Severity	-
Repair mode	Smart Repair

12


Part	Fog lamp
Position	Front left
Damages	Broken
Severity	-
Repair mode	Lumpsum replacement

13


Part	Fog lamp
Position	Back left
Damages	Broken
Severity	-
Repair mode	Lumpsum replacement

14


Part	Windscreen
Position	Front
Damages	Broken
Severity	-
Repair mode	Lumpsum replacement