

Inspection Protocol



RENAULT TRAFIC III SKÅP NORDIC LINE L2H1

Vehicle information

License plate	PXX287	Inspected by	R.A.
Year model	2018	Date of inspection	2025-10-23
Manuf. year/month	2018-05	City	Falkenberg
First day in traffic	2018-05	Keys	2
Colour	Vit	Service book	Ja
Mileage	166 060 km	Latest service	2022-09-07
Fuel	Diesel	Mileage at the latest service	83 630 km
Transmission	Manuell	Summer tires	16" plåtfälg 7/7/7/7
Engine effect	92 kW	Winter tires	plåtfälg dubbat 5/5/5/5

Damages

Location	Damage	Comments	Costs excluding VAT
Door, Front left	Scratches below 30 mm		60 €
Other, Other	Other	Sliten ratt	-
Wing, Rear left	Dents below 30 mm		60 €
Bumper, Rear	Small scratches, under 3 cm		60 €
Door, Rear left	Dents below 30 mm	Transport dörr	60 €
Door, Rear right	Dents below 30 mm	Transport dörr	60 €
Door, Right sliding door	Dents below 30 mm	Samt reva	60 €
Bumper, Front	Dents	Små inbuktningar samt revor	240 €
Bonnet	Dents below 30 mm		60 €
Glass, Windshield	Cracks long (Above 150 mm)		510 €
Service	Incomplete service book		370 €
Service	Due now		370 €
Other, Other	Other	Gnisslande rem	-
Other, Other	Other	Trögt att få in växlarna	-

Total excl. VAT	1 910 €
-----------------	---------

Service occasions

1500-MIL, 7000-MIL, 8000-MIL, 10000-MIL, 12000-MIL, 14000-MIL

Images

[See all images in large format](#)













SERVICEBEVIS (1/6)

VIN: *2020-03-12 Km: 42652*

Datum: <i>2020-03-12</i> Km: <i>42652</i> Typ av åtgärd: Service <i>4000 mil</i> Korrosionskontroll: OK ☒ Inte OK* ☐ *Se relevant sida	Fakturanr: Märkesrepresentantens Nybergs Bil AB Personlig servicetekniker Mauricio Caroca Tel: 036-30 46 93, Vxl: 036-30 46 00	Kommentarer/beskrivning
Datum: <i>7/7-22</i> Km: <i>83632</i> Typ av åtgärd: Service <i>8000 mil</i> Korrosionskontroll: OK ☒ Inte OK* ☐ *Se relevant sida	Fakturanr: Märkesrepresentantens Nybergs Bil AB Personlig servicetekniker Mauricio Caroca Tel: 036-30 46 93, Vxl: 036-30 46 00	Kommentarer/beskrivning
Datum: _____ Km: _____ Typ av åtgärd: Service ☐ Korrosionskontroll: OK ☐ Inte OK* ☐ *Se relevant sida	Fakturanr: Märkesrepresentantens	Kommentarer/beskrivning

6.12















 Image_hbRNE03nLjDSuWUIOw4Jow.jpg









