



RENAULT TRAFIC (30)

TRAFIC FGN L1H1 2800 KG BLUE DCI 110

CONFORT

VIN NO VF1FL000569595738
Registration Number GG564MK



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	1	97538 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2022-05-01	-

Inspection Report Summary

Customer	BCAauto Encheres	Report Number	P20250929105446
Inspection Date / Place	2025-09-29 / BCA GUERLESQUIN	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Not Movable	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	White	Engine Size (cc)	1997
Engine Size	2.0	No of Doors	4
Body Type	Box Wagon	Drive Train	Front
Seat Colour		No of Seats	3
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			





Equipment


Central locking	Rear parking sensors	Cruise control	Power assisted steering
Radio	Stability control	Front fog lamps	

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Cosmetic Damage

27 Dommages



1 Dommages



Component		Damage	Comments
1	Seat Cushion / Front Left	Interior / Worn - out	
2	Fender / Front Left	Paint / Scratch / Scuff	
3	Fender / Front Left	Paint / Scratch / Scuff	
4	Fender / Front Left	Paint / Scratch / Scuff	
5	Fender / Front Left	Paint / Scratch / Line	
6	Fender / Front Left	Paint / Scratch / Line	
7	Side Panel / Back Left	Bodywork / Dent / Dent	
8	Side Panel / Back Left	Paint / Chipping	
9	Side Panel / Back Left	Paint / Scratch / Line	
10	Tailgate	Bodywork / Dent / Dent	
11	Tailgate	Paint / Stone Chip	
12	Tailgate	Paint / Scratch / Scuff	


13	Side Panel / Back Right	Paint / Scratch / Scuff
14	Side Panel / Back Right	Paint / Scratch / Line
15	Side Panel / Back Right	Bodywork / Dent / Dent
16	Side Panel / Back Right	Paint / Scratch / Line
17	Side Panel / Back Right	Paint / Scratch / Scuff
18	Side Panel / Back Right	Paint / Scratch / Scuff
19	Fender / Front Right	Paint / Scratch / Scuff
20	Fender / Front Right	Paint / Chipping
21	Fender / Front Right	Paint / Scratch / Scuff
22	Fender / Front Right	Bodywork / Dent / Dent
23	Fender / Front Right	Bodywork / Dent / Dent
24	Hood	Paint / Scratch / Scuff
25	Hood	Paint / Scratch / Scuff
26	Hood	Paint / Stone Chip
27	Windshield / Front	Glass Break
28	Windshield / Front	Glass Break / Impact



1. Seat Cushion / Front Left
Interior / Worn - out -



2. Fender / Front Left
Paint / Scratch / Scuff -



3. Fender / Front Left
Paint / Scratch / Scuff -



4. Fender / Front Left
Paint / Scratch / Scuff -




5. Fender / Front Left
Paint / Scratch / Line -



6. Fender / Front Left
Paint / Scratch / Line -



7. Side Panel / Back Left
Bodywork / Dent / Dent -




8. Side Panel / Back Left
Paint / Chipping -



9. Side Panel / Back Left
Paint / Scratch / Line -



10. Tailgate
Bodywork / Dent / Dent -




11. Tailgate
Paint / Stone Chip -



12. Tailgate
Paint / Scratch / Scuff -



13. Side Panel / Back Right
Paint / Scratch / Scuff -




14. Side Panel / Back Right
Paint / Scratch / Line -




15. Side Panel / Back Right
Bodywork / Dent / Dent -




16. Side Panel / Back Right
Paint / Scratch / Line -



17. Side Panel / Back Right
Paint / Scratch / Scuff -



18. Side Panel / Back Right
Paint / Scratch / Scuff -




19. Fender / Front Right
Paint / Scratch / Scuff -



20. Fender / Front Right
Paint / Chipping -



21. Fender / Front Right
Paint / Scratch / Scuff -



22. Fender / Front Right
Bodywork / Dent / Dent -



23. Fender / Front Right
Bodywork / Dent / Dent -



24. Hood
Paint / Scratch / Scuff -



25. Hood
Paint / Scratch / Scuff -



26. Hood
Paint / Stone Chip -



27. Windshield / Front
Glass Break -



28. Windshield / Front
Glass Break / Impact -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.