



RENAULT TRAFIC: 1VJL142				
Vinnumber:	VF1FL000761542957	Versionname:	L2H1 1.6 dCi 95 Gr. Confort 2.9T	
First Registrationdate:	26/11/2018	Fiscalpower:		
Expertise Mileage:	186433	Power Kw:	70	
Bodytype:		Body colour	White	
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel	
Transmission:		Parking lot	3804	
Fueltype:	Diesel			
Type of rims (mounted)	Steel			
Certificate of Conformity	Yes			
Category	Light Commercial Vehicle			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Rear parking sensors		
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar fixed	
Type of GPS	GPS base			
Type of Lining	Lining fabrics			
Type of climate control	Manual climate control			
Limited Technical Inspection				
Tyres				
Summer tyres:	205/65/16/107 T			
	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				3.0
Tyre profile depth RL				5.0
Tyre profile depth RR				4.0
Tyre size FL				205/65 R 16 107 T
Tyre size FR				205/65 R 16 107 C
Tyre size RL				205/65 R 16 107 T
Tyre size RR				205/65 R 16 107 C
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256
Assistance equipment				
Emergency spare wheel	Yes	Jack	Yes	
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT		2338,61		
Interior, Damaged, Acceptable		0,00		



Wing trim RL, Hole, Replace

98,10



Bumper R, Deformed / Strained, Replace

230,75



Boot carpet, Damaged, Replace

137,61



Rear light L, Broken, Replace

128,94



Boot door panel RL, Dent(s) and scratch(es), Replace and paint

0,00



Boot door panel RR, Dent(s) and scratch(es), Replace and paint

0,00



Boot cover, Broken, Replace 27,25



Boot moulding, Broken, Replace 186,35



Wheel cover FR, Scratch(es), Replace 44,52



Door FR, Dent(s) and scratch(es), Repair and paint (complete) 325,87



Door trim FR, Scratch(es), Replace 116,18



A-pillar right, Dent(s) and scratch(es), Repair and paint (complete) 169,54



Wing trim FR, Scratch(es), Replace 32,01



Door RR, Dent(s) and scratch(es), Repair and paint (complete) 325,87





Door trim RR, Scratch(es), Replace

151,04



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

315,48



Wing trim RR, Scratch(es), Replace

49,10



Wheel cover RR, Scratch(es), Acceptable

0,00



Bodywork, Not original part, Remove lettering

0,00



Bodywork, Accident, Check

0,00

