



RENAULT TRAFIC: 1VJL142

Vinnumber:	VF1FL000761542957	Versionname:	L2H1 1.6 dCi 95 Gr. Confort 2.9T
First Registrationdate:	26/11/2018	Fiscalpower:	
Expertise Mileage:	186433	Power Kw:	70
Bodytype:		Body colour	White
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel
Transmission:		Parking lot	3804
Fueltype:	Diesel		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Light Commercial Vehicle		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar fixed
Type of GPS	GPS base		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Tyres

205/65/16/107 T			
Summer tyres:	Fr.L.	Continental: 2 mm	Fr.R. Continental: 3 mm
	Re.L.	Continental: 5 mm	Re.R. Continental: 4 mm
Tyre profile depth FL			2.0
Tyre profile depth FR			3.0
Tyre profile depth RL			5.0
Tyre profile depth RR			4.0
Tyre size FL			205/65 R 16 107 T
Tyre size FR			205/65 R 16 107 C
Tyre size RL			205/65 R 16 107 T
Tyre size RR			205/65 R 16 107 C
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			256
Tyre make RL			256
Tyre make RR			256

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	5972,57
-------------------	---------

Interior, Damaged, Acceptable	0,00
-------------------------------	------





Wing trim RL, Hole, Replace

98,10



Bumper R, Deformed / Strained, Replace

230,75



Boot carpet, Damaged, Replace

137,61



Rear light L, Broken, Replace

128,94



Boot door panel RL, Dent(s) and scratch(es), Replace and paint

1816,98



Boot door panel RR, Dent(s) and scratch(es), Replace and paint

1816,98



Boot cover, Broken, Replace 27,25



Boot moulding, Broken, Replace 186,35



Wheel cover FR, Scratch(es), Replace 44,52



Door FR, Dent(s) and scratch(es), Repair and paint (complete) 325,87



Door trim FR, Scratch(es), Replace 116,18



A-pillar right, Dent(s) and scratch(es), Repair and paint (complete) 169,54



Wing trim FR, Scratch(es), Replace 32,01



Door RR, Dent(s) and scratch(es), Repair and paint (complete) 325,87





Door trim RR, Scratch(es), Replace

151,04



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

315,48



Wing trim RR, Scratch(es), Replace

49,10



Wheel cover RR, Scratch(es), Acceptable

0,00



Bodywork, Not original part, Remove lettering

0,00



Bodywork, Accident, Check

0,00

