



Dacia Duster: S863ZV

Vinnumber:	VF1HJD20170864360	Versionname:	Duster 1.0 TCe 74kW Bi-Fuel 4x2 Journey
First Registrationdate:	19/05/2023	Fiscalpower:	
Expertise Mileage:	74283	Power Kw:	74
Bodytype:		Body colour	Gris Urban metaallak
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Type of rims (mounted)	Aluminium
Fueltype:	Petrol	Parking lot	260
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Telephone equipment
Number keys remote	2	Central consol F
GPS		Luggage cover
GPS storage		Front parking sensors
GPS storage	HD	Rear parking sensors
Autom climate control		Tow bar removable
Windows electric F		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 60 / 17 / 96 / H / Aluminium	4,0 mm	Continental	Summer
	Right	215 / 60 / 17 / 96 / H / Aluminium	5,0 mm	Continental	Summer
Rear	Left	215 / 60 / 17 / 96 / H / Aluminium	4,0 mm	Continental	Summer
	Right	215 / 60 / 17 / 96 / H / Aluminium	5,0 mm	Continental	Summer

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Interior, Stain, Cleaning



Wing RL, Dent(s), Repair and paint (complete)



Sill trim L, Scratch(es), Smart repair



Door RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Bonnet, Chemical polution, Polish



Outside rear-view mirror housing R, Scratch(es), Polish



Door RR, Dent(s), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Bumper trim R, Scratch(es), Smart repair



Bumper moulding R, Scratch(es), Replace



Roof, Chemical polution, Polish

