



RENAULT GRAND SCENIC

Grand Scenic 1.9 dCi 130 Expression 5 pl

VIN NO VF1JMT4N637204468
Registration Number AT909RL



MOT Date



Last Service



Number of Owners




Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Auto Encheres	Report Number	P20251016170957
Inspection Date / Place	2025-10-16 / BCA ROPPE	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1870
Engine Size	1.9	No of Doors	5
Family	Passenger Car	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	159
Engine Rating CV		Metalic Colour	Yes
Accident Damage	No	Euro Emission	

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			






Equipment

Central locking	Alloys wheels	Front fog lamps	Radio
Cruise control	Power assisted steering		


Equipment Details

Seat Heating	No	Air Conditioning	Yes
--------------	----	------------------	-----

36 Dommages




29 Dommages



5/19 - Report Number P20251016170957

13	Floor Carpet	Interior / Dirty
14	Luggage Space Cover / Back	Interior / Stained
15	Rim / Back Left	Out of Bodywork / Scratch
16	Side Panel / Back Right	Paint / Scratch / Line
17	Bumper / Front	Paint / Scratch / Line
18	Floor Carpet	Interior / Dirty
19	Tailgate	Paint / Scratch / Line
20	Fender / Front Right	Paint / Scratch / Line
21	Seat / Back Left	Interior / Stained
22	Dashboard / Front	Interior / Scraped
23	Floor Carpet	Interior / Dirty
24	Center Console	Interior / Stained
25	Seat / Front Left	Interior / Stained
26	Bumper / Back	Paint / Scratch / Line
27	Seat / Front Left	Interior / Stained
28	Rim / Front Right	Out of Bodywork / Scratch
29	Door / Back Left	Paint / Scratch / Line
30	Door / Back Right	Bodywork / Dent / Deformation
31	Side Panel / Back Left	Paint / Scratch / Line
32	Rim / Back Right	Out of Bodywork / Scratch
33	Door / Front Right	Bodywork / Dent / Deformation
34	Fender / Front Left	Paint / Scratch / Line
35	Front Light / Front Left	Glass Break
36	Seat / Back Left	Interior / Stained
37	Corner Bumper / Front Left	Paint / Scratch / Line
38	Rocker Panel / Center Right	Paint / Corrosion
39	Corner Bumper / Front Right	Paint / Chipping
40	Trunk Upholstery / Back	Interior / Stained
41	Rocker Panel / Center Right	Bodywork / Dent / Deformation


42	Side Panel / Back Left	Paint / Chipping
43	Bumper / Front	Paint / Chipping
44	Steering Wheel / Front	Interior / Scratched
45	Seat / Front Right	Interior / Loose
46	Roof	Paint / Scratch / Line
47	Panel Filling / Back Right	Interior / Scraped
48	Tailgate	Bodywork / Dent / Deformation
49	Trunk Upholstery / Back	Interior / Scraped
50	Panel Filling / Front Left	Interior / Scraped
51	Door / Front Right	Paint / Scratch / Line
52	Trunk Upholstery / Back	Interior / Scraped
53	Door / Front Left	Paint / Chipping
54	Bumper / Back	Bodywork / Breakage
55	Panel Filling / Back Left	Interior / Scraped
56	Mirror Shell / Front Left	Paint / Scratch / Line
57	Side Panel / Back Right	Bodywork / Dent / Deformation
58	Windshield / Front	Paint / Chipping
59	Panel Filling / Front Right	Interior / Scraped
60	Side Panel / Back Right	Bodywork / Dent / Deformation
61	Seat / Front Left	Interior / Ripped
62	Door / Front Right	Paint / Scratch / Line
63	Bumper / Front	Paint / Chipping
64	Door / Back Left	Paint / Scratch / Line
65	Door / Back Left	Bodywork / Dent / Deformation




1. Seat / Back Right
Interior / Stained -




2. Panel Filling / Front Left
Interior / Dirty -



3. Panel Filling / Front Right
Interior / Dirty -



4. Seat / Front Right
Interior / Stained -



5. Rim / Front Left
Out of Bodywork / Scratch -




6. Panel Filling / Back Right
Interior / Dirty -



7. Steering Wheel / Front Interior / Worn - out -




8. Panel Filling / Back Left Interior / Dirty -



9. Hood Paint / Chipping -



10. Trunk Carpet Interior / Dirty -



11. Door / Front Left Bodywork / Dent / Deformation -




12. Trunk Upholstery / Back Interior / Stained -




13. Floor Carpet
Interior / Dirty -




14. Luggage Space Cover / Back
Interior / Stained -



15. Rim / Back Left
Out of Bodywork / Scratch -



16. Side Panel / Back Right
Paint / Scratch / Line -



17. Bumper / Front
Paint / Scratch / Line -




18. Floor Carpet
Interior / Dirty -



19. Tailgate
Paint / Scratch / Line -



20. Fender / Front Right
Paint / Scratch / Line -




21. Seat / Back Left
Interior / Stained -



22. Dashboard / Front
Interior / Scraped -



23. Floor Carpet
Interior / Dirty -




24. Center Console
Interior / Stained -




25. Seat / Front Left
Interior / Stained -



26. Bumper / Back
Paint / Scratch / Line -




27. Seat / Front Left
Interior / Stained -




28. Rim / Front Right
Out of Bodywork / Scratch -



29. Door / Back Left
Paint / Scratch / Line -



30. Door / Back Right
Bodywork / Dent / Deformation -



31. Side Panel / Back Left
Paint / Scratch / Line -



32. Rim / Back Right
Out of Bodywork / Scratch -




33. Door / Front Right
Bodywork / Dent / Deformation -



34. Fender / Front Left
Paint / Scratch / Line -



35. Front Light / Front Left
Glass Break -



36. Seat / Back Left
Interior / Stained -




37. Corner Bumper / Front Left
Paint / Scratch / Line -



38. Rocker Panel / Center Right
Paint / Corrosion -



39. Corner Bumper / Front Right
Paint / Chipping -



40. Trunk Upholstery / Back
Interior / Stained -




41. Rocker Panel / Center Right
Bodywork / Dent / Deformation -




42. Side Panel / Back Left
Paint / Chipping -




43. Bumper / Front
Paint / Chipping -



44. Steering Wheel / Front
Interior / Scratched -



45. Seat / Front Right
Interior / Loose -



46. Roof
Paint / Scratch / Line -



47. Panel Filling / Back Right
Interior / Scraped -



48. Tailgate
Bodywork / Dent / Deformation -



49. Trunk Upholstery / Back Interior / Scraped -




50. Panel Filling / Front Left Interior / Scraped -



51. Door / Front Right Paint / Scratch / Line -



52. Trunk Upholstery / Back Interior / Scraped -



53. Door / Front Left Paint / Chipping -



54. Bumper / Back Bodywork / Breakage -




55. Panel Filling / Back Left
Interior / Scraped -



56. Mirror Shell / Front Left
Paint / Scratch / Line -



57. Side Panel / Back Right
Bodywork / Dent / Deformation -




58. Windshield / Front
Paint / Chipping -



59. Panel Filling / Front Right
Interior / Scraped -




60. Side Panel / Back Right
Bodywork / Dent / Deformation -



61. Seat / Front Left
Interior / Ripped -



62. Door / Front Right
Paint / Scratch / Line -



63. Bumper / Front
Paint / Chipping -



64. Door / Back Left
Paint / Scratch / Line -



65. Door / Back Left
Bodywork / Dent / Deformation -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.