



RENAULT Scenic 2012 Diesel
scenic 1.6 dci Bose (energy) S&S 130cv

VIN NO VF1JZ00BD46423026

Registration Number EM149SK



MOT Date

2024-06-20

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date

2012-06-26

Odometer Reading

171739 km

Country First Registered

Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250901141024
Inspection Date / Place	2025-09-01 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	5
Body Type	MPV	Drive Train	Front
Seat Colour	Black	No of Seats	7
Seat Covering Name		Seat Covering	Cloth/Leather
Charging Cables		NEDC CO2 Rating (q/km)	115

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment

Central locking	Rear parking sensors	Digital Radio	Front parking sensors
Sunroof	Parcel Shef	Remote central locking	Trip Computer
Power assisted steering	Alloys wheels	Electrically folding wing mirrors	Satellite navigation
Volante multifuncion	Remote adjusting wing mirrors	Cruise control	Stability control


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Winter
	205/55//R17 - 95V / 2 mm
	205/55//R17 - 95V / 2 mm
	205/55//R17 - 95V / 2 mm
	205/55//R17 - 95V / 2 mm

Cosmetic Damage

27 Danni



9 Danni



Component		Damage	Comments
1	Seat / Front Left	Interior / Ripped	
2	Seat / Front Right	Interior / Ripped	
3	Gear Knob	Interior / Broken	
4	Roof Upholstery	Interior / Broken	
5	Steering Wheel / Front	Interior / Worn - out	
6	Floor Carpet	Interior / Burn	
7	Rearview Mirror / Front Center	Interior / Broken	
8	Windshield / Front	Glass Break / Impact	
9	Hood	Bodywork / Dent / Hail Area	
10	Bumper / Front	Missing Part	
11	Bumper / Front	Bodywork / Dent	
12	Fender / Front Left	Bodywork / Dent	
13	Rim / Front Left	Out of Bodywork / Scratch	

14	Mirror Shell / Front Left	Paint / Scratch / Line
15	Door / Front Left	Bodywork / Dent
16	Door / Back Left	Bodywork / Dent
17	Fender / Back Left	Bodywork / Dent
18	Rim / Back Left	Out of Bodywork / Scratch
19	Rocker Panel / Center Left	Bodywork / Dent
20	Pillar / Front Left	Bodywork / Dent
21	Pillar / Front Left	Bodywork / Dent / Hail Area
22	Bumper / Back	Bodywork / Breakage
23	Tailgate	Bodywork / Dent
24	Monogram/Emblem / Back Center	Missing Part
25	Fender / Back Right	Bodywork / Dent
26	Door / Back Right	Bodywork / Dent
27	Rocker Panel / Center Right	Bodywork / Dent
28	Door / Front Right	Bodywork / Dent
29	Mirror Repeater / Right	Missing Part
30	Mirror Shell / Front Right	Paint / Scratch / Line
31	Fender / Front Right	Bodywork / Dent
32	Rim / Front Right	Out of Bodywork / Scratch
33	Pillar / Front Right	Bodywork / Dent / Hail Area
34	Roof	Bodywork / Dent / Hail Area
35	Cabin	Interior / Worn - out
36	Center Console	Interior / Broken



1. Seat / Front Left
Interior / Ripped -




2. Seat / Front Right
Interior / Ripped -




3. Gear Knob
Interior / Broken -




4. Roof Upholstery
Interior / Broken -



5. Steering Wheel / Front
Interior / Worn - out -



6. Floor Carpet
Interior / Burn -



7. Rearview Mirror / Front Center
Interior / Broken -



8. Windshield / Front
Glass Break / Impact -



9. Hood
Bodywork / Dent / Hail Area -



10. Bumper / Front
Missing Part -



11. Bumper / Front
Bodywork / Dent -



12. Fender / Front Left
Bodywork / Dent -



13. Rim / Front Left
Out of Bodywork / Scratch -



14. Mirror Shell / Front Left
Paint / Scratch / Line -



15. Door / Front Left
Bodywork / Dent -



16. Door / Back Left
Bodywork / Dent -




17. Fender / Back Left
Bodywork / Dent -




18. Rim / Back Left
Out of Bodywork / Scratch -



19. Rocker Panel / Center Left
Bodywork / Dent -



20. Pillar / Front Left
Bodywork / Dent -



21. Pillar / Front Left
Bodywork / Dent / Hail Area -



22. Bumper / Back
Bodywork / Breakage -



23. Tailgate
Bodywork / Dent -



24. Monogram/Emblem / Back Center
Missing Part -



25. Fender / Back Right
Bodywork / Dent -



26. Door / Back Right
Bodywork / Dent -



27. Rocker Panel / Center Right
Bodywork / Dent -



28. Door / Front Right
Bodywork / Dent -



29. Mirror Repeater / Right
Missing Part -




30. Mirror Shell / Front Right
Paint / Scratch / Line -



31. Fender / Front Right
Bodywork / Dent -




32. Rim / Front Right
Out of Bodywork / Scratch -



33. Pillar / Front Right
Bodywork / Dent / Hail Area -



34. Roof
Bodywork / Dent / Hail Area -



35. Cabin
Interior / Worn - out -



36. Center Console
Interior / Broken -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	⚠		
Clutch			
Clutch Functioning	⚠		
Equipments Test			
Other Equipments	✓	AC / Heating System	⚠
Levels			
Brakes Fluid	✓	Coolant Fluid	⚠

Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	⚠		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓	Test Drive Comment	A/C NON RAFFREDDA.
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	⚠
Engine Noise	⚠		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
⚠ Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			