



RENAULT MASTER FOURGON
MASTER FGN TRAC F3500 L3H2 BLUE DCI
135 GRAND CONFORT

VIN NO VF1MA000168944803
Registration Number GF156EC



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	2	177676 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2022-03-14	-

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20251009150555
Inspection Date / Place	2025-10-09 / BCA BETHUNE	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	White	Engine Size (cc)	2299
Engine Size	2.3	No of Doors	4
Body Type	Box Wagon	Drive Train	Front
Seat Colour		No of Seats	3
Charging Cables		WLTP CO2 Emissions	
Accident Damage	No	Euro Emission	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			



Equipment


Central locking	Rear parking sensors	Front fog lamps	Radio
Cruise control	Power assisted steering		

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Cosmetic Damage

29 Dommages



2 Dommages



Component		Damage	Comments
1	Side Panel / Back Right	Paint / Scratch / Scuff	
2	Door / Front Right	Paint / Scratch / Scuff	
3	Side Panel / Back Left	Paint / Scratch / Scuff	
4	Side Panel / Back Right	Bodywork / Dent / Deformation	
5	Fender / Front Left	Bodywork / Dent / Deformation	
6	Tailgate	Bodywork / Dent / Deformation	
7	Bumper / Front	Missing Part	
8	Floor Carpet	Interior / Dirty	
9	Side Panel / Back Right	Paint / Scratch / Scuff	
10	Side Panel / Back Left	Paint / Scratch / Scuff	
11	Fender / Front Right	Bodywork / Dent / Deformation	
12	Corner Bumper / Back Left	Paint / Scratch / Scuff	

13	Bumper / Back	Paint / Scratch / Scuff
14	Rim / Front Left	Out of Bodywork / Scratch
15	Back Light / Left	Missing Part
16	Front Light / Front Left	Missing Part
17	Rim / Front Right	Out of Bodywork / Scratch
18	Corner Bumper / Back Right	Paint / Scratch / Scuff
19	Back Light / Right	Missing Part
20	Side Panel / Back Left	Bodywork / Dent / Deformation
21	Front Light / Front Right	Missing Part
22	Rim / Back Right	Out of Bodywork / Scratch
23	Roof	Bodywork / Dent / Deformation
24	Rim / Back Left	Out of Bodywork / Scratch
25	Mirror / Front Left	Paint / Scratch / Scuff
26	Side Panel / Back Left	Bodywork / Dent / Deformation
27	Interior door handle Front left	Interior / Missing
28	Door / Back Right	Bodywork / Dent / Deformation
29	Mirror / Front Right	Bodywork / Breakage
30	Mirror / Front Left	Bodywork / Breakage
31	Side Panel / Back Left	Bodywork / Dent / Dent



1. Side Panel / Back Right
Paint / Scratch / Scuff -



2. Door / Front Right
Paint / Scratch / Scuff -



3. Side Panel / Back Left
Paint / Scratch / Scuff -



4. Side Panel / Back Right
Bodywork / Dent / Deformation -




5. Fender / Front Left
Bodywork / Dent / Deformation -



6. Tailgate
Bodywork / Dent / Deformation -



7. Bumper / Front
Missing Part -




8. Floor Carpet
Interior / Dirty -



9. Side Panel / Back Right
Paint / Scratch / Scuff -



10. Side Panel / Back Left
Paint / Scratch / Scuff -



11. Fender / Front Right
Bodywork / Dent / Deformation -




12. Corner Bumper / Back Left
Paint / Scratch / Scuff -




13. Bumper / Back
Paint / Scratch / Scuff -



14. Rim / Front Left
Out of Bodywork / Scratch -



15. Back Light / Left
Missing Part -




16. Front Light / Front Left
Missing Part -




17. Rim / Front Right
Out of Bodywork / Scratch -



18. Corner Bumper / Back Right
Paint / Scratch / Scuff -



19. Back Light / Right
Missing Part -



20. Side Panel / Back Left
Bodywork / Dent / Deformation -



21. Front Light / Front Right
Missing Part -



22. Rim / Back Right
Out of Bodywork / Scratch -




23. Roof
Bodywork / Dent / Deformation -



24. Rim / Back Left
Out of Bodywork / Scratch -




25. Mirror / Front Left
Paint / Scratch / Scuff -



26. Side Panel / Back Left
Bodywork / Dent / Deformation -



27. Interior door handle Front left
Interior / Missing -



28. Door / Back Right
Bodywork / Dent / Deformation -



29. Mirror / Front Right
Bodywork / Breakage -



30. Mirror / Front Left
Bodywork / Breakage -



31. Side Panel / Back Left
Bodywork / Dent / Dent -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.