



RENAULT MASTER FOURGON

MASTER FGN TRAC F3500 L3H2 DCI 135

GRAND CONFORT

VIN NO VF1MA000767250039
Registration Number GC383ZY



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	2	210136 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2021-11-18	-

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20251009113749
Inspection Date / Place	2025-10-09 / BCA BETHUNE	Cosmetic Grade	9

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	White	Engine Size (cc)	2300
Engine Size	2.3	No of Doors	4
Body Type	Box Wagon	Drive Train	Front
Seat Colour		No of Seats	3
Charging Cables		WLTP CO2 Emissions	
Accident Damage	No	Euro Emission	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			



Equipment


Central locking	Rear parking sensors	Front fog lamps	Radio
Cruise control	Power assisted steering		

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Cosmetic Damage

34 Dommages



1 Dommages



Component		Damage	Comments
1	Side Panel / Back Left	Bodywork / Dent / Deformation	
2	Side Panel / Back Right	Paint / Scratch / Scuff	
3	Side Panel / Back Right	Bodywork / Dent / Deformation	
4	Side Panel / Back Left	Paint / Scratch / Scuff	
5	Bumper / Front	Paint / Scratch / Scuff	
6	Side Panel / Back Right	Bodywork / Dent / Deformation	
7	Side Panel / Back Right	Paint / Scratch / Scuff	
8	Rocker Panel / Center Left	Missing Part	
9	Door / Front Right	Paint / Scratch / Scuff	
10	Windshield / Front	Glass Break / Impact	
11	Side Panel / Back Left	Paint / Scratch / Scuff	
12	Rocker Panel / Center Right	Missing Part	

13	Corner Bumper / Front Left	Paint / Scratch / Scuff
14	Corner Bumper / Front Right	Paint / Scratch / Scuff
15	Fender / Front Right	Bodywork / Dent / Deformation
16	Trunk Stick	Missing Part
17	Floor Carpet	Interior / Dirty
18	Corner Bumper / Back Right	Missing Part
19	Bumper / Back	Paint / Scratch / Scuff
20	Rim / Front Left	Out of Bodywork / Scratch
21	Door / Front Left	Bodywork / Dent / Deformation
22	Back Light / Left	Glass Break
23	Rim / Front Right	Out of Bodywork / Scratch
24	Corner Bumper / Back Left	Paint / Scratch / Scuff
25	Rim / Back Right	Out of Bodywork / Scratch
26	Mirror / Front Right	Bodywork / Breakage
27	Mirror / Front Right	Bodywork / Breakage
28	Rocker Panel / Center Left	Bodywork / Dent / Deformation
29	Mirror / Front Left	Bodywork / Breakage
30	Mirror / Front Left	Bodywork / Breakage
31	Mud Barrier / Front Right	Bodywork / Breakage
32	Fender / Front Left	Bodywork / Dent / Dent
33	Back Light / Right	Glass Break
34	Trunk Stick	Missing Part
35	Fender / Front Left	Paint / Scratch / Line



1. Side Panel / Back Left
Bodywork / Dent / Deformation -



2. Side Panel / Back Right
Paint / Scratch / Scuff -



3. Side Panel / Back Right
Bodywork / Dent / Deformation -



4. Side Panel / Back Left
Paint / Scratch / Scuff -



5. Bumper / Front
Paint / Scratch / Scuff -



6. Side Panel / Back Right
Bodywork / Dent / Deformation -



7. Side Panel / Back Right
Paint / Scratch / Scuff -



8. Rocker Panel / Center Left
Missing Part -



9. Door / Front Right
Paint / Scratch / Scuff -



10. Windshield / Front
Glass Break / Impact -



11. Side Panel / Back Left
Paint / Scratch / Scuff -



12. Rocker Panel / Center Right
Missing Part -



13. Corner Bumper / Front Left
Paint / Scratch / Scuff -




14. Corner Bumper / Front Right
Paint / Scratch / Scuff -



15. Fender / Front Right
Bodywork / Dent / Deformation -



16. Trunk Stick
Missing Part -



17. Floor Carpet
Interior / Dirty -



18. Corner Bumper / Back Right
Missing Part -



19. Bumper / Back
Paint / Scratch / Scuff -



20. Rim / Front Left
Out of Bodywork / Scratch -



21. Door / Front Left
Bodywork / Dent / Deformation -



22. Back Light / Left
Glass Break -



23. Rim / Front Right
Out of Bodywork / Scratch -



24. Corner Bumper / Back Left
Paint / Scratch / Scuff -



25. Rim / Back Right
Out of Bodywork / Scratch -



26. Mirror / Front Right
Bodywork / Breakage -



27. Mirror / Front Right
Bodywork / Breakage -



28. Rocker Panel / Center Left
Bodywork / Dent / Deformation -



29. Mirror / Front Left
Bodywork / Breakage -



30. Mirror / Front Left
Bodywork / Breakage -



31. Mud Barrier / Front Right
Bodywork / Breakage -




32. Fender / Front Left
Bodywork / Dent / Dent -



33. Back Light / Right
Glass Break -



34. Trunk Stick
Missing Part -



35. Fender / Front Left
Paint / Scratch / Line -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.