

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia									
				Policyholder				Opposite party				Opposite party company							
				Operation 2025		Claim number		Code / Agency				Date accident 18/09/2025							
				Expert code		Adjuster code		Policy number				Injured person can recover the VAT							
Date assignment 18/09/2025		Date first survey 25/09/2025		Place POMEZIA		C/O VAR		Repairs TO START		Photo Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)											Formerly plate								
Lessee / Co-owner											Date of overhaul								
Vehicle (Brand - Model - Version) RENAULT MASTER FG TA L2 H2 T33 dCi 135 start MY23 furgone 135CV 4P								Plate GT429XX		Vin Chassis VF1MA000772850462		First Registration 29/03/2024							
Usage status NON CONOSCIUTO		Km 39637		Tyres % 50		Color BIANCO		Type of enamel METALLIZED/DOUBLE		Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																			
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0							Wheelbase		Seats No. 0		Axles 0		
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses													
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts	
								Dif Time		Dif Time		Dif Time		Time		+		(VAT excluded)	
1	Aggregate size of 3 elements							S		S		S							
1	850224674R	Rear central bumper						S		S		S							
1	850176896R	Rear side bumper						L	S		S		S						
1	850160036R	Rear side bumper						R	S		S		S						
1	620104124X	Front bumper							S		S		S						
1	623109004R	Grille							S		S		S						
1	260105567R	Headlight						R	S		S		S						
1	265500023R	Rear headlamp						R	S		S		S						
1	768F30005R	Trim of rear mudguard rear part						R	S		S		S						
1	768F30006R	Trim of rear mudguard rear part						R	S		S		S						
1	261603141R	Fanalino lat. retrovisore est. 16W						R	S		S		S						
1	963017417R	External electrically adjustable rear-view mirror						R	S		S		S						
1	261652475R	Fanalino lat. retrovisore est. 16W						L	S		S		S						
1	638406859R	Internal stone guard of front part of front wheel arch						R	S		S		S						
1	638411709R	Internal stone guard of front part of front wheel arch						L	S		S		S						
1	760325069R	Side rear wall						R	G		G		G						
1	821000245R	Rear door						R	M		M		M						
1	631008686R	Front mudguard						R	M		M		M						
1	651005058R	Front bonnet							M		M		M						
1	901002052R	Rear hinged loading door						R	L		L		L						
1	801009976R	Front door						R	L		L		L						
1	Codice Ricambio	Igienizzazione interni - tessuto																	

New for old value (N)	Remarks
	PNEUM ESTIVI BRIDGESTONE 225/65/16C VHL SPORCO, MALSTOCCATO E RILEV SEGNALE SU QUADRO STRUM.: FARE MANUTENZIONE, RIGENERARE FAP INUTILE E RISERVA ADBLUE