



Renault Master: 1VLC073

Vinnumber:	VF1ML000960705038	Versionname:	Master Combi L1H1 30 2.3dCi 145pk/cv 5p
First Registrationdate:	13/12/2018	Fiscalpower:	
Expertise Mileage:	19047	Power Kw:	107
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	NOT OK		
Battery functioning	Yes		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Type of Tow bar	Tow bar removable
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	SD present		

Tyres

	225/65/16/112 R			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 10 mm	Re.R.	Continental: 10 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				10.0
Tyre profile depth RR				10.0
Tyre size FL				225/65 R 16 112 R
Tyre size FR				225/65 R 16 112 R
Tyre size RL				225/65 R 16 112 R
Tyre size RR				225/65 R 16 112 R
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

MOT certificate, Non-conforme, Replace



Service, Maintenance, Check



Ignition key, Missing, Replace



Bumper F, Scratch(es), Smart repair



Outside rear-view mirror housing L, Scratch(es), Acceptable



Roof pillar L, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Acceptable



Wing trim RR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Acceptable



Roof pillar R, Dent(s) and scratch(es), Repair and paint (complete)



Roof, Dent(s) and scratch(es), Repair and paint (complete)





Aerial, Damaged, Replace

