

Vehicle details

VIN	VF1R87006 63978985	Brand	RENAULT	Maintenance date	-
Licence Plate	G4-30-JD	Model	Captur Energy TCe 90 ActieAuto 5d Intens APL	Maintenance mileage	-
Registration date	04/10/2019	Year	2019	Exterior Color	Orange Metallic
Odometer	90 884 km	Engine size	898	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	03/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres




Exterior

1



Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

2



Part	Roof wind deflector
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

3



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

4



Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

5



Part	Alloy wheel 17"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

6



Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

7



Part	Roof post A/B/C
Position	Right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair