

Vehicle details

VIN	VF1R98001 64220534	Brand	RENAULT	Maintenance date	-
Licence Plate	J6-73-SZ	Model	Clio Estate Energy TCe 90 ACTI 5d Limited 5d	Maintenance mileage	-
Registration date	16/10/2020	Year	2020	Exterior Color	White Solid
Odometer	93 374 km	Engine size	898	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	13/11/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓


Removable element

Load cover	✓
------------	---

Technical Document

User manual	✓
Spare key	✓
Card Key	✓
Sat Nav CD ROM Software	✓

Tyres



Exterior

2		<table border="0"> <tr><td>Part</td><td>Step plate</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dent & Chips</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Step plate	Position	Back right	Damages	Dent & Chips	Severity	-	Repair mode	For info	3		<table border="0"> <tr><td>Part</td><td>Spoiler</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scatched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Spoiler	Position	Front left	Damages	Scatched	Severity	-	Repair mode	Repair
Part	Step plate																								
Position	Back right																								
Damages	Dent & Chips																								
Severity	-																								
Repair mode	For info																								
Part	Spoiler																								
Position	Front left																								
Damages	Scatched																								
Severity	-																								
Repair mode	Repair																								

Interior damage

1		<table border="0"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Interior cleaning	Position	Front	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning
Part	Interior cleaning											
Position	Front											
Damages	Stained/dirty											
Severity	-											
Repair mode	Cleaning											