



Renault Clio: G579ZS

Vinnumber:	VF1R9800264272724	Versionname:	Clio 0.9 TCe 66kW Zen estate
First Registrationdate:	21/01/2020	Fiscalpower:	
Expertise Mileage:	77312	Power Kw:	66
Bodytype:		Body colour:	Blanc Glacier niet-metaallak
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Type of rims (mounted):	Steel
Fueltype:	Petrol	Parking lot:	378
Number of seats:	5		
Type of rims (mounted):	Steel		
Maintenance needed:	Yes		

Options

Number of keys total	1	Telephone equipment
GPS		Luggage cover
Manual climate control		Tow bar removable
Windows electric F		
Radio multimedia		

Degree of wear

195/55/16/87 H				
Winter tyres:	Fr.L.	Bridgestone: 5,1 mm	Fr.R.	Bridgestone: 4,8 mm
	Re.L.	Bridgestone: 5,5 mm	Re.R.	Bridgestone: 5 mm
Tyre profile depth FL				5.1
Tyre profile depth FR				4.8
Tyre profile depth RL				5.5
Tyre profile depth RR				5.0
Tyre size FL				195/55 R 16 087 H
Tyre size FR				195/55 R 16 087 H
Tyre size RL				195/55 R 16 087 H
Tyre size RR				195/55 R 16 087 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute



Ignition key, Missing, Replace

No pictures to display

Interior, Stain, Cleaning



Wing FL, Chemical polution, Polish



Bonnet, Dent(s), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Door RR, Chemical polution, Polish



Door FR, Dent(s), Repair and paint (complete)



Wing FR, Chemical polution, Polish



Boot lid covering R, Scratch(es), Replace



Bumper corner RR, Scratch(es), Repair and paint (complete)



Bumper corner RL, Scratch(es), Repair and paint (complete)



Roof, Dent(s), Repair and paint (complete)

