

## Vehicle details

|                   |                    |              |                                                |                           |             |
|-------------------|--------------------|--------------|------------------------------------------------|---------------------------|-------------|
| VIN               | VF1R98004 64220530 | Brand        | RENAULT                                        | Maintenance date          | -           |
| Licence Plate     | J9-64-JX           | Model        | Clio Estate Energy TCe 90 ActieAuto 5d Limited | Maintenance mileage       | -           |
| Registration date | 31/08/2020         | Year         | 2020                                           | Exterior Color            | White Solid |
| Odometer          | 153 779 km         | Engine size  | 898                                            | interior Color            | Black       |
| Fuel              | Petrol             | Body Type    | -                                              | Next technical inspection | -           |
| Seats             | -                  | Transmission | Manual                                         | CO2                       | -           |
| Doors             | 5                  | Gears        | 5                                              |                           |             |

## Inspection Details

|                 |            |                 |              |
|-----------------|------------|-----------------|--------------|
| Inspection date | 21/08/2025 | Inspection loc. | Dekra Ayvens |
|-----------------|------------|-----------------|--------------|



## Generic equipment

|                         |   |
|-------------------------|---|
| Manual air-conditioning | ✓ |
| Cruise control          | ✓ |
| Alloy wheel rims        | ✓ |
| Tow                     | ✓ |
| Central locking         | ✓ |
| Electric windows        | ✓ |
| Side rails              | ✓ |
| Park Distance Control   | ✓ |
| Audio System            | ✓ |

## Removable element


|            |   |
|------------|---|
| Load cover | ✓ |
|------------|---|

## Technical Document

|                  |   |
|------------------|---|
| User manual      | ✓ |
| Warranty booklet | ✓ |
| Spare key        | ✓ |
| Remote key       | ✓ |

## Tyres

### Winter kit



## Exterior

|   |                                                                                     |             |                  |   |                                                                                      |             |                  |
|---|-------------------------------------------------------------------------------------|-------------|------------------|---|--------------------------------------------------------------------------------------|-------------|------------------|
| 4 |  | Part        | Roof post A/B/C  | 7 |  | Part        | Lower bumper     |
|   |                                                                                     | Position    | Left             |   |                                                                                      | Position    | Back             |
|   |                                                                                     | Damages     | Chemical deposit |   |                                                                                      | Damages     | Scratched        |
|   |                                                                                     | Severity    | -                |   |                                                                                      | Severity    | Length (cm) > 10 |
|   |                                                                                     | Repair mode | Lumpsum repair   |   |                                                                                      | Repair mode | Repair           |

|    |                                                                                    |                                                        |                                                                |
|----|------------------------------------------------------------------------------------|--------------------------------------------------------|----------------------------------------------------------------|
| 8  |   | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Door<br>Back right<br>Chemical deposit<br>-<br>Lumpsum repair  |
| 9  |  | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Door<br>Front right<br>Chemical deposit<br>-<br>Lumpsum repair |
| 10 |   | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Sill<br>Right<br>Chemical deposit<br>-<br>Lumpsum repair       |
| 11 |  | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Wing<br>Front right<br>Chemical deposit<br>-<br>Lumpsum repair |
| 12 |   | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Bonnet<br>-<br>Chemical deposit<br>-<br>Lumpsum repair         |
| 13 |  | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Windscreen<br>-<br>Stone impact<br>-<br>For info               |
| 14 |  | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Roof<br>-<br>Chemical deposit<br>-<br>Lumpsum repair           |

### Interior damage

|   |                                                                                      |                                                        |                                                              |
|---|--------------------------------------------------------------------------------------|--------------------------------------------------------|--------------------------------------------------------------|
| 1 |   | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Radio code<br>-<br>Missing<br>-<br>For info                  |
| 2 |   | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Interior cleaning<br>Front<br>Stained/dirty<br>-<br>Cleaning |
| 3 |  | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Fabric seat<br>Front left<br>Worn out<br>-<br>For info       |
| 5 |   | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Interior tailgate lining<br>-<br>Scratched<br>-<br>Replace   |
| 6 |  | Part<br>Position<br>Damages<br>Severity<br>Repair mode | Boot carpet<br>Back<br>Stained/dirty<br>-<br>Cleaning        |

15



|             |                   |
|-------------|-------------------|
| Part        | Interior cleaning |
| Position    | Back              |
| Damages     | Stained/dirty     |
| Severity    | -                 |
| Repair mode | Cleaning          |