


Vehicle details

VIN	VF1R98006 61700327	Brand	RENAULT	Maintenance date	-
Licence Plate	TT-63-4N	Model	CLIO Energy TCe 90 Eco Limited 5d	Maintenance mileage	-
Registration date	16/01/2019	Year	2019	Exterior Color	White Solid
Odometer	93 854 km	Engine size	898	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	02/06/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓


Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres



Exterior

1		Part Position Damages Severity Repair mode	Roof - Dented Diameter (mm) > 20 Smart Repair	2		Part Position Damages Severity Repair mode	Roof wind deflector Back Scratched Length (cm) > 10 Repair
3		Part Position Damages Severity Repair mode	Bumper Front right Scratched Length (cm) > 10 Repair	4		Part Position Damages Severity Repair mode	Alloy wheel 16" Front right Scratched - Lumpsum repair
5		Part Position Damages Severity Repair mode	Roof post A/B/C Right Dented Diameter (mm) > 20 Smart Repair	6		Part Position Damages Severity Repair mode	Bumper Back Scratched Length (cm) > 10 Repair
7		Part Position Damages Severity Repair mode	Door moulding Front left Scratched - For info				