




Renault Scenic: 1VWJ685				
Vinnumber:	VF1RFA00162858830	Versionname:		
First Registrationdate:	20/03/2019	Fiscalpower:		
Expertise Mileage:	124251	Power Kw:	88	
Bodytype:		Body colour	Grey	
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	2505	
Fueltype:	Diesel			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Options				
Number of keys total	2	Luggage cover		
Cruise Control		Front parking sensors		
Steering wheel multifunctional		Rear parking sensors		
Radio multimedia		Type of Tow bar	Tow bar fixed	
Type of headlighting	Headlighting LED			
Type of GPS	GPS big screen color			
Type of Lining	Lining semi-artificial leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Tyres				
Summer tyres:	195/35/20/92 H			
	Fr.L.	Semperit: 5 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				195/35 R 20 92 H
Tyre size FR				195/35 R 20 92 H
Tyre size RL				195/35 R 20 92 H
Tyre size RR				195/35 R 20 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2477
Tyre make FR				2477
Tyre make RL				261
Tyre make RR				261
Assistance equipment				
Spare wheel	Yes	Jack		Yes
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT				1662,00
Seat cover FL, Damaged, Acceptable				0,00



Door panel RR, Tear, Replace	147,63
------------------------------	--------



Roof liner, Damaged, Replace	362,64
------------------------------	--------



Armrest, Damaged, Replace	84,66
---------------------------	-------




Step L, Dent(s), Acceptable	0,00
-----------------------------	------




Alloy rim RL polished, Rust, Acceptable	0,00
---	------



Alloy rim FL polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Tyre FL, Deformed / Strained, Acceptable	0,00
--	------



Rear light R, Broken, Replace	97,89
-------------------------------	-------



Bumper R, Scratch(es), Repair and paint (complete)	289,07
--	--------





Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Outside rear-view mirror housing R, Broken, Replace	124,32
---	--------



Door RR, Dent(s), Acceptable	0,00
------------------------------	------



Wing RR, Dent(s), Acceptable	0,00
------------------------------	------



Step R, Scratch(es), Repair and paint (complete)	157,71
--	--------



Alloy rim RR polished, Scratch(es), Acceptable	0,00
--	------



Bodywork, Not original part, Remove lettering	0,00
---	------

