


Vehicle details

VIN	VF1RFA002 70543189	Brand	RENAULT	Maintenance date	-
Licence Plate	T6-72-HF	Model	Grand Sc��nic TCE 140 EDC Equilibre 5d	Maintenance mileage	-
Registration date	26/06/2023	Year	2023	Exterior Color	Silver Metallic
Odometer	57 618 km	Engine size	1333	Interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	22/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
7 seater	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Load cover	✓
------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 195/55/20 All seasons 4.0 mm		Michelin 195/55/20 All seasons 4.5 mm	
Continental 195/55/20 All seasons 6.5 mm		Continental 195/55/20 All seasons 7.0 mm	

Exterior

2



Part	Step plate
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	For info

3



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

4



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

5



Part	Roof
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

6



Part	Door
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

7



Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

8



Part	Roof post A/B/C
Position	Side left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

9



Part	Wing
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

10



Part	Step plate
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	For info

Interior damage

1



Part

Fabric seat

Position

Centre

Damages

Stained/dirty

Severity

-

Repair mode

Cleaning

11



Part

Fabric seat

Position

Front left

Damages

Stained/dirty

Severity

-

Repair mode

Cleaning