


Vehicle details

VIN	VF1RFA002 70543189	Brand	RENAULT	Maintenance date	-
Licence Plate	T6-72-HF	Model	Grand Sc��nic ��nic TCe 140 EDC Equilibre 5d	Maintenance mileage	-
Registration date	26/06/2023	Year	2023	Exterior Color	Silver Metallic
Odometer	57 618 km	Engine size	1333	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	22/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	��
Cruise control	��
GPS system	��
7 seater	��
Automatic Gearbox	��
Metallic paint	��
Central locking	��
Electric windows	��
Park Distance Control	��
Audio System	��
Led lighting	��

Removable element

Load cover	��
------------	----


Technical Document

User manual	��
Warranty booklet	��
Spare key	��
Remote key	��
Sat Nav CD ROM Software	��


Tyres

Michelin 195/55/20 All seasons 4.0 mm		Michelin 195/55/20 All seasons 4.5 mm	
Continental 195/55/20 All seasons 6.5 mm		Continental 195/55/20 All seasons 7.0 mm	

Exterior

2		PartStep plate PositionBack right DamagesDent & Chips Severity- Repair modeFor info	3		PartBumper PositionBack DamagesScratched Severity- Repair modeRepair
4		PartWing PositionBack right DamagesDented SeverityDiameter (mm) > 20 Repair modeSmart Repair	5		PartRoof Position- DamagesDented SeverityDiameter (mm) > 20 Repair modeSmart Repair
6		PartDoor PositionFront right DamagesDent & Chips Severity- Repair modeRepair	7		PartDoor PositionBack left DamagesDented SeverityDiameter (mm) > 20 Repair modeSmart Repair
8		PartRoof post A/B/C PositionSide left DamagesDent & Chips Severity- Repair modeRepair	9		PartWing PositionBack left DamagesDented SeverityDiameter (mm) > 20 Repair modeSmart Repair
10		PartStep plate PositionBack left DamagesDent & Chips Severity- Repair modeFor info			

Interior damage

1		PartFabric seat PositionCentre DamagesStained/dirty Severity- Repair modeCleaning			
11		PartFabric seat PositionFront left DamagesStained/dirty Severity- Repair modeCleaning			