


### Vehicle details

VIN	VF1RFA006 70543339	Brand	RENAULT	Maintenance date	-
Licence Plate	S7-24-TV	Model	Grand Scīc ½nic TCe 140 EDC Equilibre 5d	Maintenance mileage	-
Registration date	24/04/2023	Year	2023	Exterior Color	Black Metallic
Odometer	31 608 km	Engine size	1333	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

### Inspection Details

Inspection date	04/06/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



### Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
7 seater	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


### Removable element

Load cover	✓
------------	---

### Technical Document



User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

### Tyres




Bridgestone 195/55/20 All seasons 2.0 mm  
 Bridgestone 195/55/20 All seasons 2.0 mm  
 Bridgestone 195/55/20 All seasons 5.0 mm  
 Bridgestone 195/55/20 All seasons 4.0 mm

### Exterior

<b>2</b>		<table border="0"> <tr><td>Part</td><td>Exterior door mirror shell</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Exterior door mirror shell	Position	Front right	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair	<b>3</b>		<table border="0"> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Roof	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair
Part	Exterior door mirror shell																								
Position	Front right																								
Damages	Chemical deposit																								
Severity	-																								
Repair mode	Lumpsum repair																								
Part	Roof																								
Position	-																								
Damages	Chemical deposit																								
Severity	-																								
Repair mode	Lumpsum repair																								

**Interior damage**

<b>1</b>		<table border="0"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Interior cleaning	Position	Front left	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning
Part	Interior cleaning											
Position	Front left											
Damages	Stained/dirty											
Severity	-											
Repair mode	Cleaning											