

DEKRA Automotive Solutions

Vehicle details

VIN	VF1RFB002 64757290	Brand	RENAULT	Maintenance date	04/09/2024
Licence Plate	JNP39H	Model	Megane4Estate-2016	Maintenance mileage	93 248 km
Registration date	28/05/2020	Year	2020	Exterior Color	Other
Odometer	115 359 km	Engine size	-	interior Color	
Fuel	Diesel	Body Type	Estate	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	25/08/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Central locking	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element

Refill emergency kit	✓
Load cover	✓
Towing hook	✓

Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Spare key	✓

DEKRA Automotive Solutions

Tyres

Nexen 205/55/16 V Summer 7.0 mm		Nexen 205/55/16 V Summer 7.0 mm	
Nexen 205/55/16 V Summer 6.0 mm		Nexen 205/55/16 V Summer 6.0 mm	
			
			

Winter kit

Nokian 205/55/16 R Winter 6.0 mm		Nokian 205/55/16 R Winter 8.0 mm	
Michelin 205/55/16 R Winter 8.0 mm		Michelin 205/55/16 R Winter 8.0 mm	
			
			

Damages

1



Part	Service
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum

2



Part	Aftermarket wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

3



Part	Aftermarket wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	Lumpsum replacement

4



Part	Aftermarket wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

5



Part	Interior roof lining
Position	Back
Damages	Broken
Severity	-
Repair mode	Lumpsum replacement

6



Part	Interior tailgate lining
Position	Back
Damages	Scratched
Severity	-
Repair mode	For info

7



Part	Other mechanical
Position	-
Damages	Defective
Severity	-
Repair mode	For info
steering play	

8



Part	Registration plates
Position	Front
Damages	Scratched
Severity	-
Repair mode	For info

9



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Lumsum Paintworks

10



Part	Sill
Position	Right
Damages	Dented
Severity	-
Repair mode	Lumpsum repair

11		Part Position Damages Severity Repair mode	Wing Front left Scratched - For info
12		Part Position Damages Severity Repair mode	Door sill Front left Dented - Smart Repair
13		Part Position Damages Severity Repair mode	Door Frame seal Front left Broken - Lumpsum replacement
14		Part Position Damages Severity Repair mode	Door Front left Dented - For info
15		Part Position Damages Severity Repair mode	Fabric door lining Back left Dent & Chips - Lumpsum repair
16		Part Position Damages Severity Repair mode	Door sill Back left Dented - Lumpsum repair
17		Part Position Damages Severity Repair mode	Headlight Back left Scratched - Polishing
18		Part Position Damages Severity Repair mode	Bumper Back Dented - For info
19		Part Position Damages Severity Repair mode	Headlight Back right Scratched - For info
20		Part Position Damages Severity Repair mode	Fabric door lining Back right Scratched - For info
21		Part Position Damages Severity Repair mode	Door sill Front right Dented - For info
22		Part Position Damages Severity Repair mode	Fabric door lining Front right Scratched - For info
23		Part Position Damages Severity Repair mode	Alloy wheel Front right Scratched - For info
24		Part Position Damages Severity Repair mode	Headlight Front right Scratched - Polishing
25		Part Position Damages Severity Repair mode	Headlight Front left Scratched - Polishing
26		Part Position Damages Severity Repair mode	Bonnet - Dented - Smart Repair

DEKRA Automotive Solutions

27		PartTailgate spoiler Position- DamagesScratched Severity- Repair modeFor info	28		PartRoof Position- DamagesDented Severity- Repair modeFor info
29		PartWindscreen Position- DamagesBroken Severity- Repair modeLumpsum replacement	30		PartOther interior Position- DamagesNot conform Severity- Repair modeReplace dismantling of equipment