



## Renault Megane: T913JF

|                         |                          |                        |                                              |
|-------------------------|--------------------------|------------------------|----------------------------------------------|
| Vinnumber:              | <b>VF1RFB00270881052</b> | Versionname:           | <b>Megane 1.3 TCE 103kW Equilibre estate</b> |
| First Registrationdate: | <b>30/06/2023</b>        | Fiscalpower:           |                                              |
| Expertise Mileage:      | <b>68543</b>             | Power Kw:              | <b>103</b>                                   |
| Bodytype:               |                          | Body colour            | <b>Gris Titanium metaallak</b>               |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type             | <b>Metalic</b>                               |
| Transmission:           | <b>Front</b>             | Type of rims (mounted) | <b>Aluminium</b>                             |
| Fueltype:               | <b>Petrol</b>            | Parking lot            | <b>812</b>                                   |
| Number of seats         | <b>5</b>                 |                        |                                              |
| Type of rims (mounted)  | <b>Aluminium</b>         |                        |                                              |
| Maintenance needed      | <b>No</b>                |                        |                                              |

## Options

|                       |          |                            |
|-----------------------|----------|----------------------------|
| Number of keys total  | <b>1</b> | Telephone equipment        |
| GPS                   |          | Central consol F           |
| Autom climate control |          | Luggage cover              |
| Windows electric F    |          | Headlights Xenon/LED/Laser |
| Radio multimedia      |          | Front parking sensors      |
|                       |          | Rear parking sensors       |

## Tyres

| Location | Position | Measures                           | Depth  | Make        | Type   |
|----------|----------|------------------------------------|--------|-------------|--------|
| Front    | Left     | 205 / 55 / 16 / 91 / V / Aluminium | 7,8 mm | Continental | Winter |
|          | Right    | 205 / 55 / 16 / 91 / V / Aluminium | 7,8 mm | Continental | Winter |
| Rear     | Left     | 205 / 55 / 16 / 91 / H / Aluminium | 6,2 mm | Michelin    | Winter |
|          | Right    | 205 / 55 / 16 / 91 / H / Aluminium | 6,4 mm | Michelin    | Winter |

## Assistance equipment

|                                          |          |
|------------------------------------------|----------|
| Number of charging cables (normal)       | <b>0</b> |
| Number of charging cables (rapid charge) | <b>0</b> |

Ignition key, Missing, Replace

No pictures to display


Interior, Stain, Cleaning



Door FL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Broken, Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Roof, Scratch(es), Repair and paint (complete)

