



Renault Megane: G060ZD

Vinnumber:	VF1RFB00664643163	Versionname:	Megane 1.3 TCe 103kW Limited estate
First Registrationdate:	6/01/2020	Fiscalpower:	
Expertise Mileage:	125751	Power Kw:	103
Bodytype:		Body colour:	Noir Étoilé metaallak
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Petrol	Parking lot:	672
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Central consol F
Autom climate control		Luggage cover
Windows electric F		Front parking sensors
Radio multimedia		Rear parking sensors

Tyres

205/55/16/91 H				
Winter tyres:	Fr.L.	Michelin: 4,3 mm	Fr.R.	Michelin: 4,4 mm
	Re.L.	Michelin: 5,2 mm	Re.R.	Michelin: 4,8 mm
Tyre profile depth FL		4.3		
Tyre profile depth FR		4.4		
Tyre profile depth RL		5.2		
Tyre profile depth RR		4.8		
Tyre size FL		205/55 R 16 91 H		
Tyre size FR		205/55 R 16 91 H		
Tyre size RL		205/55 R 16 91 H		
Tyre size RR		205/55 R 16 91 H		
Tyre type FL		Winter		
Tyre type FR		Winter		
Tyre type RL		Winter		
Tyre type RR		Winter		
Tyre make FL		261		
Tyre make FR		261		
Tyre make RL		261		
Tyre make RR		261		

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Outside rear-view mirror housing L, Scratch(es), Replace and paint



Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Bumper F, Crack, Repair and paint (partial)



Bonnet, Dent(s), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Rear window, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Rear light R, Scratch(es), Replace



Roof, Chemical pollution, Polish

