

INSPECTION REPORT


End of contract

GENERAL INFO

File	303340
License plate	2ATN294
Vehicle identification number	VF1RFB00667481923
Dossier	2021 095 011
Make	Renault Mégane GT dCi 115 Corp
Mileage	145704
First registration	12/07/2021
client availability date	26/01/2026
inspectionDate	06/02/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
41	Windshield // Replace	N
81	Door Front Left // Smart Repair Medium	N
91	Rocker Panel Left // Smart Repair Medium	N
101	Door Rear Left // Smart Repair Medium	N
113	Wing Rear Left // Painting	N
134	Bumper Rear // Repair & Painting	N
154	Rear Bonnet // Repair & Painting	N
159	Rear Bonnet / Rear Window / Replace	N
181	Wing Rear Right // Smart Repair Medium	N
193	Door Rear Right // Painting	N
199	Door Rear Right / Window / Replace	Y
203	Rocker Panel Right // Repair & Painting	N
216	Door Front Right // Polish	Y
219	Door Front Right / Window / Replace	Y
225	Side View Mirror Right // Polish	Y
231	Wing Front right // Smart Repair Medium	Y
316	Tyre Front Left // Replace	N
344	Wheel Front Right / Wheel Cover / Replace	N
860	Interior Cleaning // Small	Y


Damage Pictures



Damage within Renta-norm-



Rear Bonnet // Repair & Painting-scratch





Rear Bonnet / Rear Window / Replace-scratch



Wing Rear Left // Painting-scratch




Door Front Left // Smart Repair Medium-scratch



Windshield // Replace-scratch




Wheel Front Right / Wheel Cover / Replace-scratch



Door Rear Right / Window / Replace-scratch



Door Front Right / Window / Replace-scratch



Door Front Right // Polish-scratch



Door Rear Right // Painting-scratch




Wing Rear Right // Smart Repair Medium-scratch + dent



Rocker Panel Right // Repair & Painting-scratch + dent



Bumper Front // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Left // Smart Repair Medium-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent



Side View Mirror Right // Polish-Chemical reaction



Interior Cleaning // Small-stain



Tyre Front Left // Replace-worn



Wing Front right // Smart Repair Medium-bad position