



RENAULT MEGANE GRANDTOUR: 1YVZ103

Vinnumber:	VF1RFB00766723351	Versionname:	Blue dCi 115 Intens
First Registrationdate:	7/01/2021	Fiscalpower:	
Expertise Mileage:	58172	Power Kw:	85
Bodytype:		Body colour:	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2604
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining artificial leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

	225/40/18/92 H			
Summer tyres:	Fr.L.	Other: 5 mm	Fr.R.	Other: 5 mm
	Re.L.	Other: 5 mm	Re.R.	Other: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/40 R 18 92 H
Tyre size FR				225/40 R 18 92 H
Tyre size RL				225/40 R 18 92 H
Tyre size RR				225/40 R 18 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				263
Tyre make FR				263
Tyre make RL				263
Tyre make RR				263

Assistance equipment

Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		
Total cost ex VAT			2619,67
Floor covering FL, Burned, Smart repair			113,74



Bonnet, Chemical polution, Repair and paint (complete)

395,90



Windscreen, Scratch(es), Replace

473,60



Alloy rim RL polished, Scratch(es), Repair and paint (complete)

199,04



Wing RL, Dent(s), Paintless dent repair

93,06



Alloy rim FL polished, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Repair and paint (complete)

289,07



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

199,04



Door RR, Scratch(es), Acceptable

0,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

199,04



Wing RR, Scratch(es), Acceptable

0,00



Roof, Scratch(es), Repair and paint (complete)

657,18

