



Renault Megane: T782NH

Vinnumber:	VF1RFB00771394486	Versionname:	Megane 1.3 TCE 103kW Equilibre estate
First Registrationdate:	1/08/2023	Fiscalpower:	
Expertise Mileage:	76776	Power Kw:	103
Bodytype:		Body colour	Bleu Iron speciale metaallak
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Type of rims (mounted)	Steel
Fueltype:	Petrol	Parking lot	1139
Number of seats	5		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	1	Telephone equipment
GPS		Central consol F
Autom climate control		Luggage cover
Windows electric F		Headlights Xenon/LED/Laser
Radio multimedia		Front parking sensors
		Rear parking sensors

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 55 / 16 / 91 / H / Steel	5,6 mm	Michelin	Winter
	Right	205 / 55 / 16 / 91 / H / Steel	6,1 mm	Michelin	Winter
Rear	Left	205 / 55 / 16 / 91 / H / Steel	5,2 mm	Michelin	Winter
	Right	205 / 55 / 16 / 91 / H / Steel	5,0 mm	Michelin	Winter

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Ignition key, Missing, Replace

No pictures to display

Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)

 [Damage Picture - 1](#)



Outer door handle FR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Rear light R tailgate, Waterinfiltration, Replace

