



Renault Megane: L932FD

Vinnumber:	VF1RFB00867238310	Versionname:	Megane 1.3 TCe 103kW Intens estate
First Registrationdate:	5/05/2021	Fiscalpower:	
Expertise Mileage:	74924	Power Kw:	103
Bodytype:		Body colour:	Beu Cosmos metaallak
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Petrol	Parking lot:	687
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Central consol F
Autom climate control		Luggage cover
Windows electric F		Headlights Xenon/LED/Laser
Radio multimedia		Front parking sensors
		Rear parking sensors
		Tow bar removable

Degree of wear

205/55/16/91 T				
Winter tyres:	Fr.L.	Goodyear: 5,9 mm	Fr.R.	Goodyear: 5,6 mm
	Re.L.	Goodyear: 5,2 mm	Re.R.	Goodyear: 5,6 mm
Tyre profile depth FL				5.9
Tyre profile depth FR				5.6
Tyre profile depth RL				5.2
Tyre profile depth RR				5.6
Tyre size FL				205/55 R 16 91 T
Tyre size FR				205/55 R 16 91 T
Tyre size RL				205/55 R 16 91 T
Tyre size RR				205/55 R 16 91 T
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Seat cover FL, Stain, Cleaning



Door RL, Dent(s), Repair and paint (complete)



Outer sill L, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Polish



Bonnet, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper moulding FL, Scratch(es), Replace



Wing RR, Bad repair, Repair and paint (complete)



Door RR, Dent(s), Repair and paint (complete)



Wing FR, Scratch(es), Polish

Wing L R, Scratch(es), Polish



Tailgate / Boot, Scratch(es), Polish



Bumper R, Scratch(es), Repair and paint (complete)

