



RENAULT MEGANE²BK HY: GC-318-GH

Vinnumber:	VF1RFB00867845632	Versionname:	
First Registrationdate:	7/10/2021	Fiscalpower:	
Expertise Mileage:	104975	Power Kw:	
Bodytype:	Break	Body colour:	Dark Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Category:	Passenger Car		

Options

Number of keys total	1	Rear view camera
Number keys remote	1	
GPS big screen color		
GPS storage		
GPS storage	HD	

Tyres

205/55/16/94 V				
Summer tyres:	Fr.L.	Michelin: 65%	Fr.R.	Michelin: 55%
	Re.L.	Michelin: 35%	Re.R.	Michelin: 35%
Tyre profile depth FL				4.1
Tyre profile depth FR				4.5
Tyre profile depth RL				6.0
Tyre profile depth RR				5.9
Tyre size FL				205/55 R 16 94 V
Tyre size FR				205/55 R 16 94 V
Tyre size RL				205/55 R 16 94 V
Tyre size RR				205/55 R 16 94 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Seat cover FL, Stain, Cleaning



Seat cover FL, Deformed / Strained, Repair/replace (lump sum)



Interior covering B pillar L, Scratch(es), Smart repair



Tyres, No damage, Acceptable



Outer sill L, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Paint




Door FR, Dent(s), Repair and paint (complete)




Luggage compartment cover, Missing, Replace



Boot lid covering R, Scratch(es), Smart repair





Bumper R, Scratch(es), Paint



Tailgate / Boot, Scratch(es), Paint

