


Vehicle details

VIN	VF1RFC002 60773499	Brand	RENAULT	Maintenance date	-
Licence Plate	W76752M	Model	ESPACE Energy dCi 130 Business Edition 96KW	Maintenance mileage	-
Registration date	05/12/2018	Year	1000	Exterior Color	White Solid
Odometer	131 254 km	Engine size	1598	interior Color	Brown
Fuel	Diesel	Body Type	Passenger van	Next technical inspection	01/12/2024
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	30/12/2024	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Panoramic roof	✓
Xenon projectors	✓
Anti-fog lights	✓
Front radars	✓
Reversing radars	✓
Reversing camera	✓
Heating seats	✓
Electric seats	✓

Removable element



Technical Document

User manual	✓
Log books	✓
Spare key	✓
Card Key	✓

Tyres

Winter kit

Bridgestone 235/65/17 H Winter 8.1 mm		Bridgestone 235/65/17 H Winter 8.0 mm	
Bridgestone 235/65/17 H Winter 8.1 mm		Bridgestone 235/65/17 H Winter 8.0 mm	

Exterior

1



Part	Windscreen
Position	-
Damages	Stone impact
Severity	Diameter (mm) > 10
Repair mode	Replace

2



Part	Bonnet
Position	-
Damages	Dented
Severity	-
Repair mode	Repair

3



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

4



Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

5



Part	Door sill
Position	Back left
Damages	Dented
Severity	-
Repair mode	Repair

7



Part	Bumper
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

8



Part	Tailgate / Boot door
Position	-
Damages	Scratched
Severity	-
Repair mode	Repair

9



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	For info

11



Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

Interior damage

6



Part	Interior cleaning
Position	-
Damages	Not carried out
Severity	-
Repair mode	Lumpsum

10



Part	Seat back upholstery mixed
Position	Front right
Damages	Cut
Severity	-
Repair mode	Replace

Others



12



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint

13



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks