



RENAULT ESPACE: 1VWS698

Vinnnumber:	VF1RFC00762368713	Versionname:	Blue dCi 160 EDC Corporate Edition
First Registrationdate:	22/03/2019	Fiscalpower:	
Expertise Mileage:	192755	Power Kw:	118
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2502
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Panoramic roof	
Seats F heated		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	Headlighting LED	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	Tow bar fixed
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Degree of wear

235/60/18/107 H				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				235/60 R 18 107 H
Tyre size FR				235/60 R 18 107 H
Tyre size RL				235/60 R 18 107 H
Tyre size RR				235/60 R 18 107 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Number of charging cables (normal)	0	
Number of charging cables (rapid charge)	0	
Total cost ex VAT		1536,90
Bumper F, Scratch(es), Acceptable		0,00



Windscreen, Stone chip(s), Windscreen repair

0,00



Door RL, Dent(s) and scratch(es), Repair and paint (complete)

521,40



Step L, Scratch(es), Acceptable

0,00



Bumper trim R, Scratch(es), Acceptable

0,00



Tailgate / Boot, Scratch(es), Repair and paint (complete)

494,10



Rear window, Scratch(es), Acceptable

0,00



Door RR, Scratch(es), Repair and paint (complete)

521,40



Step R, Scratch(es), Acceptable

0,00



Wing RR, Dent(s), Acceptable

0,00



Panoramic roof, Crack, Replace

0,00

