



RENAULT KADJAR: GC-331-NQ

Vinnumber:	VF1RFE00468281893	Versionname:	
First Registrationdate:	22/10/2021	Fiscalpower:	
Expertise Mileage:	153090	Power Kw:	
Bodytype:	SUV	Body colour:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Luggage cover
Number keys remote	1	Rear view camera
GPS big screen color		

Tyres

215/55/18/99 V				
Summer tyres:	Fr.L.	Continental: 80%	Fr.R.	Continental: 85%
	Re.L.	Continental: 40%	Re.R.	Continental: 55%
Tyre profile depth FL				2.8
Tyre profile depth FR				2.5
Tyre profile depth RL				5.5
Tyre profile depth RR				4.7
Tyre size FL				215/55 R 18 99 V
Tyre size FR				215/55 R 18 99 V
Tyre size RL				215/55 R 18 99 V
Tyre size RR				215/55 R 18 99 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Spare wheel	Yes	Jack	Yes
Remote ignition key (no insert), Missing, Repair/replace (lump sum)			



Malfunction indicator, Blinking, Check



Roof liner, Dirty, Cleaning



Tyres, No damage, Acceptable



Tyre FR, Out of tolerance, Replace



Tyre FL, Out of tolerance, Replace



Door FL, Dent(s), Repair and paint (complete)



Wing RL, Dent(s), Repair and paint (complete)



Bumper moulding F, Scratch(es), Acceptable



Bumper F, Scratch(es), Acceptable



Door RR, Scratch(es), Paint



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Door trim FR, Scratch(es), Replace



Boot lid covering R, Scratch(es), Smart repair



Boot carpet, Dirty, Cleaning

