

Inspection Protocol

RENAULT CLIO E-TECH MULTIMODE, 140HK, 2023

Vehicle information

License plate	ERD41E	Inspected by	S.V.
Year model	2023	Date of inspection	2025-10-23
Manuf. year/month	2022-07	City	Falkenberg
First day in traffic	2022-10	Keys	1
Colour	Vit	Service book	Ja
Mileage	16 420 km	Latest service	2024-11-08
Fuel	Bensin	Mileage at the latest service	10 550 km
Transmission	Automat	Summer tires	16" plåtfälg 5/5/5/5
Engine effect	103 kW	Winter tires	alu-fälg dubbat 8/8/8/8

Damages

Location	Damage	Comments	Costs excluding VAT
Keys, Reservnyckel	Missing		370 €
Service, Not serviced	Missad service		370 €
Other, Other	Other	Skärm laggas när man lägger i backen	-
Skärm , Front left	Smart repair	Liten buckla	70 €
Glass, Windshield	Stenskott/Spricka	ERD41E 250910, köpare betalar självrisk	430 €
Other, Other	Other	Fäste insynsskydd saknad	70 €

Total excl. VAT 1 310 €

Service occasions

500-mil

Images

[See all images in large format](#)

















SERVICEBEVIS (1/6)

VIN:

Datum: <u>19-11-23</u> Km: <u>3641</u>		Fakturanr: <u>1823641</u>	
Typ av åtgärd:		Märkesrepresentantens	
Service	<input checked="" type="checkbox"/>		Kommentarer/övrigt
Korrosionskontroll:	<input type="checkbox"/>		
OK <input checked="" type="checkbox"/>	Inte OK* <input type="checkbox"/>		
*Se relevant sida			
Datum: <u>08-11-24</u> Km: <u>10557</u>		Fakturanr: <u>1823641</u>	
Typ av åtgärd:		Märkesrepresentantens	
Service	<input type="checkbox"/>		Kommentarer/övrigt
Korrosionskontroll:	<input type="checkbox"/>		
OK <input checked="" type="checkbox"/>	Inte OK* <input type="checkbox"/>		
*Se relevant sida			
Datum:		Fakturanr:	
Typ av åtgärd:		Märkesrepresentantens	
Service	<input type="checkbox"/>		
Korrosionskontroll:	<input type="checkbox"/>		
OK <input type="checkbox"/>	Inte OK* <input type="checkbox"/>		
*Se relevant sida			

6.11





