

INSPECTION REPORT


End Of Contract

GENERAL INFO

File	287349
License plate	2CDJ866
Vehicle identification number	VF1RJA00868989958
Dossier	2021 343 265
Make	Renault Clio dCi 100 Corp.Edit
Mileage	35068.00
First registration	14/06/2022
	03/07/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
64	Wing Front Left // Repair & Painting	Y
84	Door Front Left // Repair & Painting	Y
163	Roof // Repair & Painting	Y
186	Wing Rear Right // Polish	Y
193	Door Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
314	Wheel Front Left / Wheel Cover / Replace	Y
334	Wheel Rear Right / Wheel Cover / Replace	Y
344	Wheel Front Right / Wheel Cover / Replace	Y
564	Dashboard // Replace Completely	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	Y
883	Key Price Range 2 //	Y

Damage Pictures



Wing Rear Right // Polish-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Bumper Front // Painting-scratch




Wheel Front Right / Wheel Cover / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch





Door Rear Right // Painting-scratch




Wheel Rear Right / Wheel Cover / Replace-scratch



Wing Front Left // Repair & Painting-dent



Roof // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Interior Cleaning // Small-stain



