

Renault Clio: H299BR

Vinnumber:	VF1RJA00964721783	Versionname:	Clio 1.0 TCe 74kW Zen
First Registrationdate:	13/01/2020	Fiscalpower:	
Expertise Mileage:	147215	Power Kw:	74
Bodytype:		Body colour	Noir Etoile metaallak
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Type of rims (mounted)	Steel
Fueltype:	Petrol	Parking lot	212
Number of seats	5		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	2	Telephone equipment
GPS		Luggage cover
Manual climate control		Headlights Xenon/LED/Laser
Windows electric F		
Radio multimedia		

Degree of wear

195/55/16/87 H			
Summer tyres:	Fr.L.	Continental: 4,5 mm	Fr.R.
	Re.L.	Continental: 4,7 mm	Re.R.
			Continental: 3,6 mm
Tyre profile depth FL			4.5
Tyre profile depth FR			5.6
Tyre profile depth RL			4.7
Tyre profile depth RR			3.6
Tyre size FL			195/55 R 16 87 H
Tyre size FR			195/55 R 16 87 H
Tyre size RL			195/55 R 16 87 H
Tyre size RR			195/55 R 16 87 H
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			256
Tyre make RL			256
Tyre make RR			256

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0


Door RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Wing FL, Stone chip(s), Repair and paint (complete)



Wing RL, Dent(s), Repair and paint (complete)



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Stone chip(s), Repair and paint (complete)



Outer door handle FR, Scratch(es), Polish



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Polish



Outside rear-view mirror housing R, Scratch(es), Polish



Wing FR, Scratch(es), Polish



Tailgate / Boot, Scratch(es), Polish



Bumper R, Scratch(es), Repair and paint (complete)



Rear window, Scratch(es), Polish



Roof, Scratch(es), Polish

